	2	2	2	
	(5	
	i			
	4	Ę	ζ	
	()	
	i	į		
	i			
	2	2	2	
	L	1	İ	

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: **Buildings & Structures**

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

-	FC	OROF	FFIC	EU	SE ON	LY		
Town No.:				Site No.: 10				
UTM			1	1		!	1:	1
QUAD:								

õ

1. ADDRESS

1153 Boston Post Road

(map 46, lot 70)

2 NAME

(historic)

Nathan Chittenden

NAME (common)

3. USE

(historic) USE

(present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



5. ARCHITECT

6. DATE

1750

BUILDER

STYLE

Colonial

7. ALTERATIONS
Now shingled, the original wall covering was probably clapboards. Modern asphalt roofing and additions to the rear. If the date of 1750 is correct, it is possible that there was originally a central chimney and the present paired chimneys are later.

8 NOTABLE FEATURES
The doorway is tall and narrow, giving the facade a tauter, slimmer look than is often the case with the usual broad-beamed Colonial Crisply white against the dark wall, under the shade of a handsome pair of big trees, it is an important accent on a corner

now threatened with graceless commercial growth. 9. ARCHITECTURAL-HISTORICAL Notice the role played by the white picket fence in tying this house and No. 1139 together to present a strong united front to the street. The green space between the two houses is a welcome sight in the midst of commercial clutter. (Also see 1139 Boston Post Road)

SIGNIFICANCE

DESCRIPTION

Tercentenary Committee; Dorothy Whitfield Society '76; Connecticut Historical Commission '72; Colonial Dames. Photograph: Charles Hubbard p.19

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS ☐ Clapboard ☐ Brick ☐ Asbestos Shingle ☐ Stucco ☐ Other: ■ Wood Shingle □ Fieldstone □ Concrete ☐ Asphalt Siding ☐ Board & Batten ☐ Cut Stone □ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: □ Masonry ☐ Iron or Steel ☐ Concrete ☐ Other: Post & Beam Balloon 13. **ROOF** a. B-Pitched ☐ Gable-front ☐ Hip ☐ Shed ☐ Other: □ Saltbox □ Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel □ Mansard ☐ Flat ☐ Sawtooth b.

Tower(s) □ Monitor ☐ Cupola ☐ Dormered Gable □ Dome Asphalt Shingle ☐ Metal c.

Wood Shingle ☐ Slate ☐ Other: 14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: ACRE (APPROX) 15. CONDITION: Exterior □ Excellent M. Good ☐ Fair ☐ Poor ☐ Bad 16. CONDITION: Structure DESCRIPTION □ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad 17. OUTBUILDINGS (visible from public road) ☐ Carriage House □ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) ☐ Planted Grounds ☐ Garden □ Terracing ☐ Plaza ☐ Court ☐ Stone Wall(s) Pickett Fence ☐ Iron Fence ☐ Post & Rail □ Other: 19. SURROUNDING ENVIRONMENT a. X Town Street b. D Commercial Industrial c. Ø Open ☐ Rural ☐ Wooded □ Semi-rural ☐ Agricultural ☐ Lakefront ☐ Clustered Growth Residential ☐ Coastal □ Development ☐ Vacation, now or originally ☐ Salt marsh d. Of outstanding scenic/architectural value ☐ Of scenic/architectural value Of supportive value to contiguous scenic/architectural area ☐ Neutral ☐ Other: and narrow, giving the facad 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT □ Important ☐ Other: 21. OWNERSHIP Private ☐ Interior accessible Date 7/15/81 D. PENAR 22. Name B ROLL COMPILED Photographer D. PERAR Negative Organization: Guilford Preservation Alliance P.O. Box 199, Guilford, Conn. 06437 23. THREATS TO BUILDING OFFICE USE ONLY □ None Known ☐ Highways □ Vandalism □ Developers □ Zoning □ Private Owner □ Deterioration □ Renewal 24. SUBSEQUENT EVALUATIONS ment Tercentenary Committee; Doro Commecticut Misterical Commission '72: Colon Oherles Habbard b.19 FOR

In all categories below, check more than one box if applicable.