

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No.: 87
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 149 Church Street  
(map 46, lot 134)
2. **NAME**  
*(historic)* George E. Hurlburt  
**NAME**  
*(common)*
3. **USE**  
*(historic)*  
**USE**  
*(present)* Private house and  
 doctor's offices
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** c1876 **BUILDER**  
**STYLE** Greek Revival
7. **ALTERATIONS**  
 Porch added probably early 20th century.

SIGNIFICANCE

8. **NOTABLE FEATURES**  
 Boxed cornice with returns; frieze; lintels over the windows;  
 rectangular gable window; stone foundation
9. **ARCHITECTURAL-HISTORICAL**  
 One of the later versions of a Greek Revival house in Guilford.  
 The long returns on the cornice are a feature seen from time to  
 time both in the village and out in the rural areas. The later  
 addition of a porch covers the original doorway. The scale of  
 this house is somewhat smaller than the earlier houses of similar  
 style.

SOURCES

10. **SOURCES**  
 Guilford land records, 1881 Birdseye Map.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a.  Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b.  Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c.  Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: 75' x 175'

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a.  Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b.  Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c.  Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d.  Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible as doctor's office

INDEX NO. 87

22. Name P. Odiseos

Date 7/6/81

Photographer P. Odiseos

Date 7/6/81

Negative Roll 5: 19A

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

Guilford's Neg. 5: 18A

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

Add to Sources: Dorothy Whitfield Society.