

Town No.:

Site No. 91

UTM

QUAD:

DISTRICT

IF NR SPECIFY

 S NR Actual Potential

State of Connecticut

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

IDENTIFICATION

1. **ADDRESS** 267 Church Street
Map 53, Lot 15
2. **NAME**
(*historic*)
NAME
(*common*)
3. **USE**
(*historic*)
USE
(*present*) private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** c1870 **BUILDER**
STYLE Greek Revival
7. **ALTERATIONS**
Rear addition; shingles

SIGNIFICANCE

8. **NOTABLE FEATURES**
Boxed cornice with returns; frieze; 6/6 sash; arched gable window; doorway with entablature and pilasters.
9. **ARCHITECTURAL-HISTORICAL**
This two story Greek Revival house has its entrance on a three bay wide gable end. The arched gable window is a form used in late Greek Revival houses in Guilford. The small frieze and cornice returns along with the pilaster and entablature doorway stand out clearly on this shingled house.

SOURCES

10. **SOURCES**
Guilford Land Records

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: 75' X 250'

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 91

22. Name

P. Odiseos

Date 7/6/81

Photographer

P. Odiseos

Date 7/6/81

Negative Roll # 15A

Organization:

Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Guilfd's Neg. R5: 14A

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY