

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No. 102
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

- 1. **ADDRESS** 384 Clapboard Hill Road
(map 81, lot 26)
- 2. **NAME** Henry Dudley
(historic)
NAME
(common)
- 3. **USE**
(historic)
USE Private house
(present)
- 4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

- 5. **ARCHITECT**
- 6. **DATE** 1829 **BUILDER**
STYLE Federal
- 7. **ALTERATIONS**
Side and rear additions. Doorway appears to be modern.
- 8. **NOTABLE FEATURES**
Twelve over twelve sash, six over six sash in gable; stone slab foundation.
- 9. **ARCHITECTURAL-HISTORICAL**
This small house was built a decade or so before the many Greek Revival houses were built in this area. It is a simple story and a half house that may have had another type of doorway at one time.

Henry Dudley (1799-1862) oldest son of Amos, Jr. married Vesta Bradley in 1823 and built this house just west of the river and north of the road in 1828-9.

SIGNIFICANCE

SOURCES

- 10. **SOURCES**
Joel E. Helander, Guilford Long Ago, Vol II; Dorothy Whitfield Society '76; Guilford Tax lists.

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 1 1/2 **APPROXIMATE DIMENSIONS:** **LOT SIZE:** 1.25ac

- 15. CONDITION: Exterior**
- Excellent
 - Good
 - Fair
 - Poor
 - Bad

- 16. CONDITION: Structure**
- Excellent
 - Good
 - Fair
 - Poor
 - Bad

- 17. OUTBUILDINGS (visible from public road)**
- Barn(s)
 - Carriage House
 - Garage
 - Shed(s)
 - Shop(s)
 - Other (well, stand, greenhouse, gazebo, privy, etc.):

- 18. LANDSCAPING (visible from public road)**
- Planted Grounds
 - Garden
 - Terracing
 - Plaza
 - Court
 - Stone Wall(s)
 - Pickett Fence
 - Iron Fence
 - Post & Rail
 - Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- Salt meadow*
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

- 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT**
- Vital
 - Important
 - Supportive
 - Neutral
 - Other:

- 21. OWNERSHIP**
- Public
 - Private
 - Interior accessible

INDEX NO. 102

22. Name P. Odiseos Date 7/17/81
Photographer P. Odiseos Date 7/14/81 Negative R. 9. 15
Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Glfd's Neg. R. 9: 14A

- 23. THREATS TO BUILDING**
- None Known
 - Renewal
 - Highways
 - Private Owner
 - Vandalism
 - Deterioration
 - Developers
 - Other:
 - Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY