

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No. 116
UTM	
QUAD:	
DISTRICT	
<input type="checkbox"/> S	<input type="checkbox"/> NR
IF NR SPECIFY	
<input type="checkbox"/> Actual	<input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 730 Country Road
(map 109, lot 4)
2. **NAME**
(historic) North Guilford School (1913-54)
NAME
(common) Shoreline Day School (1981)
3. **USE**
(historic) School
USE
(present) School
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** 1913 **BUILDER**
STYLE Shingle
7. **ALTERATIONS**

SIGNIFICANCE

8. **NOTABLE FEATURES**
 Wide overhanging eaves; frieze; round arch opening for front alcove with radiating shingles; 6/6 windows in front; 12/12 on the sides; cobblestone foundation.
9. **ARCHITECTURAL-HISTORICAL**
 This was built as a two-room school to replace 4 one-room schools in North Guilford in 1913. The County Road School was replaced by the Melissa Jones School, which opened in 1954. The building has been used by the Shoreline Association for the Retarded and Handicapped Inc. and as a day care center for pre-schoolers as the Shoreline Day School.

SOURCES

10. **SOURCES**
 Elizabeth Nettleton Theiss, former teacher this school; William C.H. Moe, History of Education in Guilford and Allied Educational Interests - 1936.

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: | **APPROXIMATE DIMENSIONS:** | **LOT SIZE:** 1 ACRE

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 116

22. Name P.O. & D.P.
Photographer D.P.
Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Date 7/3/81

Date 7/3/81

Negative ROLL 4:0A

GUILFORD'S NEG 4:2

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY