n	1	٠	
a	ä	a	

DESCRIPTION

SIGNIFICANO

State of Connecticut

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

**Buildings & Structures** 

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

1. ADDRESS 64 Fair Street (map 39, lot 24)

2. NAME (historic)

Seth Bishop

NAME

(common)

3. USE (historic) USE

(present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



FOR OFFICE USE ONLY

Site No.:

IF NR SPECIE

Actual

164

Potential

Town No .:

DISTRICT

S

NR

QUAD:

5. ARCHITECT

6. DATE 1796

BUILDER

Federal

7. ALTERATIONS

Side porch; shed addition to rear; chimney replaced.

8. NOTABLE FEATURES

Narrow clapboard; palladian-like window; 12/12 sash; broken pediment door hood with flat pilaster; fanlight; large red stone slab foundation.

9. ARCHITECTURAL-HISTORICAL This house is a good example of the transition from Colonial architecture to Federal architecture in Guilford. The center chimney of a Colonial house was retained, yet details such as the palladian-like window and the fanlight were added to give the house a new more sophisticated appearance.

The house was built by Joel Griffing. Joel's brother Nathanies copied this house when he built his own house some years later at 6 Fair Street. Joel Griffing was the Master of St. Alban's Lodge No. 38 of the Free and Accepted Masons. A room on the second floor of this house was used for Lodge meetings, it has a raised ceiling. Date 1796 is cut in a corner stone of the house. Griffing was also the Warden of the Borough of Guilford from 1802 to 1803.

10. SOURCES

Dorothy Whitfield Society '76; Mary Hoadley Griswold p. 104; Steiner; Dana Collection. Photograph: Guilford Library.

checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS Clapboard ☐ Brick ☐ Stucco ☐ Asbestos Shingle Other: ☐ Wood Shingle ☐ Fieldstone ☐ Asphalt Siding ☐ Concrete ☐ Board & Batten ☐ Cut Stone ☐ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: ☐ Masonry ☐ Iron or Steel ☐ Concrete ☐ Other: Post & Beam Balloon 13. **ROOF** a. 🖄 Pitched ☐ Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Saltbox ☐ Cross-gable ☐ False Dormer ☐ Flat Hip ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b. 

Tower(s) □ Monitor ☐ Dormered Gable ☐ Cupola □ Dome c. D Wood Shingle Asphalt Shingle ☐ Slate □ Metal ☐ Other: 1/4 ACRE 14. NUMBER OF STORIES: **APPROXIMATE DIMENSIONS:** 15. CONDITION: Exterior ☐ Excellent Good ☐ Fair ☐ Poor □ Bad 16. CONDITION: Structure DESCRIPTION □ Excellent ☑ Good ☐ Fair ☐ Poor □ Bad 17. OUTBUILDINGS (visible from public road) ☐ Barn(s) ☐ Carriage House ☐ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) Planted Grounds ☐ Garden □ Terracing ☐ Plaza ☐ Court ☐ Stone Wall(s) ☐ Pickett Fence ☐ Iron Fence ☐ Post & Rail ☐ Other: 19. SURROUNDING ENVIRONMENT a. I Town Street b. 

Commercial c. D Open Rural ☐ Industrial ☐ Wooded ☐ Semi-rural ☐ Agricultural Lakefront Clustered Growth Residential Coastal □ Development ☐ Vacation, now or originally ☐ Salt marsh d. 

Of outstanding scenic/architectural value ☐ Of scenic/architectural value ☐ Of supportive value to contiguous scenic/architectural area ☐ Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT Vital □ Supportive □ Neutral M Important ☐ Other: 21. OWNERSHIP ☐ Public Private ☐ Interior accessible P. Odiseos 22. Name BY Negative (P. | . 161 COMPILED Photographer P. Odiseoi Organization: **Guilford Preservation Alliance** P.O. Box 199, Guilford, Conn. 06437 23. THREATS TO BUILDING ONLY ☐ Developers ☐ Highways □ None Known Vandalism □ Zonina ☐ Renewal ☐ Private Owner □ Deterioration ☐ Other:

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the

In all categories below, check more than one box if applicable.

FOR OFFICE USE ONLY

24. SUBSEQUENT EVALUATIONS

Add to Sources: Photograph: Guilford Keeping Society.