2	2		
	2		
ä			
q			
	2		
n			
d			

State of Connecticut

CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

FOR OFFI	CE USE ONLY
Town No.:	Site No.: 255
UTM	1 1 1 1 1 1 1
QUAD:	
DISTRICT IF	NR SPECIFY Actual Potential

DENTIFICATION

DESCRIPTION

1. ADDRESS 2349 Long Hill Road (map 101, lot 23)

2. NAME (historic) NAME

John Stone II

(common)

3. USE (historic) USE

(present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



5. ARCHITECT

6. DATE

1773

BUILDER

Colonial

7. ALTERATIONS

Siding; rear shed roof addition; 2/2 sash; windows added on the sides; shingles.

8. NOTABLE FEATURES

Moulding under the eaves; plain door frame; stone chimney; stone foundation.

9. ARCHITECTURAL-HISTORICAL

Although it no longer retains its old window sash, the form of this Colonial house and placement of the windows are notable features. The stone chimney and molding under the eaves also contribute to its appearance. With its large lot it plays a supportive role in its neighborhood and is a reminder of the continuing rural nature of this district.

John Stone II, is believed to have been the first owner of this house. The property has been owned by the Hubbard family, at least, since 1852 (cf. Map) and is still held by a Hubbard.

10. SOURCES

Tercentenary Committee; Dorothy Whitfield Society; Dana Collection; 1852 Irvine Map.

SIGNIFICANCE

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS ☐ Clapboard ☐ Brick ☐ Stucco Asbestos Shingle ☐ Other: ☐ Fieldstone □ Wood Shingle □ Concrete ☐ Asphalt Siding ☐ Board & Batten ☐ Cut Stone ☐ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: ☐ Masonry ☐ Iron or Steel ☐ Concrete Other: Post & Beam Balloon 13. **ROOF** a. X Pitched ☐ Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Saltbox ☐ Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b. D Tower(s) ☐ Monitor ☐ Dormered Gable ☐ Cupola □ Dome c. D Wood Shingle X Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: **APPROXIMATE DIMENSIONS:** 46.4 ACRES 14. NUMBER OF STORIES: LOT SIZE: 15. CONDITION: Exterior ☐ Excellent ☐ Good ☐ Fair N Poor ☐ Bad 16. CONDITION: Structure DESCRIPTION □ Excellent ☐ Good ☐ Fair ☐ Poor □ Bad 17. OUTBUILDINGS (visible from public road) ☑ Barn(s) ☐ Carriage House ☐ Garage Shed(s) / ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) ☐ Garden ☐ Planted Grounds □ Terracing ☐ Plaza ☐ Court ☐ Stone Wall(s) ☐ Pickett Fence ☐ Iron Fence ☐ Post & Rail Other: 19. SURROUNDING ENVIRONMENT a.

Town Street b.

Commercial c. Q Open ☐ Rural ☐ Wooded ☐ Industrial ☑ Semi-rural ☐ Agricultural Lakefront Clustered Growth -Residential Coastal ☐ Development ☐ Vacation, now or originally ☐ Salt marsh d.

Of outstanding scenic/architectural value ☐ Of scenic/architectural value ☑ Of supportive value to contiguous scenic/architectural area ☐ Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT ☐ Important Supportive ☐ Neutral ☐ Other: 21. OWNERSHIP ☐ Public ☑ Private □ Interior accessible D. PENAR Date 7/6/8/ 22. Name BY Photographer D. PENAR Negative 22:18A Date 7/6/8/ LED COMP Organization: Guilford Preservation Alliance P.O. Box 199, Guilford, Conn. 06437 GLF175, 22:19 F 23. THREATS TO BUILDING ONLY ☐ None Known □ Vandalism □ Developers ☐ Highways □ Zoning ☐ Renewal ☐ Private Owner □ Deterioration ☐ Other: FOR OFFICE USE 24. SUBSEQUENT EVALUATIONS

In all categories below, check more than one box if applicable.