

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

| GENERAL INFORM | | | | | | |
|-----------------------------|--|-----------------|--------------------------|-------------------|------------|------------------|
| Building Name (Comme | on) 538 Long Hill Roa | d | | | | |
| Building Name (Histori | c) Edmund Page Hous | se | | | | |
| Street Address or Locat | ion 538 Long Hill Roa | d | | | | |
| Town/City Guilford | Vi | llage | C | ounty New H | Haven | |
| Owner(s) Gerald and | Linda Beauchemin | | | | Public | X Private |
| PROPERTY INFOR | | | | | | |
| Present Use: | | | | | | |
| Historic Use: Resident | tial: single dwelling | | | | | |
| Accessibility to public | : Exterior visible from | public road?X | Yes 🗌 No | | | |
| Interior accessible? | Yes X No If ye | - | | | | |
| Style of building Greek | yle of building Greek Revival Date of Construction 1842 (Helander) | | | | | ander) |
| Material(s) (Indicate use | or location when appropriate |): | | | | |
| Clapboard | Asbestos Siding | Brick | Wood Shing | le [| Asphalt Si | ding |
| Fieldstone | Board & Batten | Stucco | Cobblestone | | Aluminun | n Siding |
| Concrete (Typ | e) | Cut Stone | е (Туре |) [| Other | |
| Structural System | | | | | | |
| 🗙 Wood Frame | Post & Beam | Balloon | Load bearing r | nasonry | Structur | al iron or steel |
| Other | | | | | | |
| Roof (<i>Type</i>) | | | | | | |
| X Gable | 🗌 Flat | Mansard | Monitor | Sawt | ooth | |
| Gambrel | Shed | Hip | Round | Other | | |
| (Material) | | | | | | |
| Wood Shingle | Roll Asphalt | Tin | Slate | X Asphalt Shingle | | |
| | Tile | | | _ | | |
| Number of Stories: | A 1/2 | pproximate Dime | ensions <u>25' x 40'</u> | | | |
| Structural Condition: | Excellent | 🗙 Good | 🗌 Fair | Deter | riorated | |
| Exterior Condition: | Excellent | 🗙 Good | 🗌 Fair | Deter | riorated | |
| Location Integrity: | On original site | Moved | When? | | _ | |
| Alterations? Yes | \mathbf{X} No \Box If yes, e | explain: | | | | |
| FOR OFFICE USE: | Town # 5 | Site # | UTM | | | |
| | District: S | NR 🗌 If NR, | Specify: Ac | tual | Potential | |

PROPERTY INFORMATION (CONT'D)

| Related outbuilding | gs or landscape fe | atures: | | | |
|---------------------|---------------------|-----------------|-------------------------|------------|---------|
| 🗙 Barn | X Shed | 🗙 Garage | Carriage House | Shop | Garden |
| Other lands | cape features or bu | ildings: | | | |
| Surrounding Enviro | onment: | | | | |
| Open land | Woodland | Residential | Commercial | Industrial | 🗙 Rural |
| 🗙 High buildi | ng density | Scattered build | dings visible from site | | |

• Interrelationship of building and surroundings:

This property consists of 0.88 acres of land on the west side of Long Hill Road. A driveway extends to the west off the road and terminates in front of (to the south) the barn. A secondary tier of the driveway terminates in front of (to the east) of the garage. The garage is to the west of the house and the barn is to the north. The property sits at the corner of Long Hill Road and Copper Hill Drive. (See continuation sheet)

• Other notable features of building or site (Interior and/or Exterior)

This is a two-story dwelling with an attic and a front-gable roof with cornice returns. The roof is covered in asphalt shingles. The house is Greek Revival in style and sheathed in aluminum siding. The façade faces east. The façade is three bays wide with the main doorway located in the southern bay of the first-story facade, accessed by a low stone porch. (See continuation sheet)

| Architect Unknown | Builder Unknown | |
|-------------------|-----------------|--|
| | DUNCET | |

• Historical or Architectural importance:

This dwelling was originally owned by Edmund Page and was built in 1842. Page was born in 1802 in Branford to Joel Page and Mabel Smith. He married Nancy Gordon in 1827 and they had five children: Eli Fowler Page, John C. Page, James L. Page, James Baldwin Page, and Joel Canfield Page. The 1850 and 1870 United States Federal Census of Guilford lists Edmund Page as a farmer living with his wife and children. Later owners of the property were Roswell Corey, Moses Lupshitz, Samuel Shapiro, and Eugene Slugoski.

• Sources:

Guilford Tax Assessor property records accessed at http://www.propertyrecordcards.com/PropertyResults.aspx? towncode=060&uniqueid=5488 on October 25, 2015. Helander, Joel Eliot. "A Treasury of Guilford Places." Guilford, Connecticut: Joel Helander, 2008. Ancestry.com. 1850 and 1870 United States Federal Census of Guilford, Connecticut.

| Photographer Kristen Nietering | | | Date 1/21/2015 | | |
|---|------------------|------------|------------------|---------|--|
| View East view of the house, camera facing southwest. | | | Negative on File | | |
| Name Kristen Nietering | | | Date 10/25/2015 | | |
| Organization Guilford Preserva | ation Alliance | | | | |
| Address 199 PO Box Guilford, | | | | | |
| • Subsequent field evaluations: | | | | | |
| Latitude & Longitude: 41.30229 | 98, -72.699882 | | | | |
| Threats to the building or site: | | | | | |
| X None known ☐ Hight | ways 🗌 Vandalism | Developers | Renewal | Private | |
| Deterioration Zonin | ng Other | | Explanation _ | | |



State Historic Preservation Office

HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

538 Long Hill Rd.

Interrelationship of building and surroundings

A mile to the northwest is the Guilford High School. Surrounding the property are nineteenth and twentieth century single-family dwellings.

Other notable features of building or site

Fenestration consists of symmetrically-spaced six-over-six double-hung windows, two on the first story and three on the second. A rectangular decorative window is centered in the façade attic gable. The Greek Revival features include the front-facing gable roof, cornice returns, and vertical window fenestration. Additions to the main structure extend off the north and west elevations.

