SOURCES

10. 500

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

1. ADDRESS

1178 Moose Hill Road (map 72, lot 5)

2. NAME

(historic)

NAME

(common)

3. **USE**

(historic)

USE (present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



FOR OFFICE USE ONLY

Site No.:

IF NR SPECIFY

Actual

Town No .:

DISTRICT

QUAD:

1

5. ARCHITECT

6. DATE

c1850

BUILDER

STYLE Vernacular Greek Revival

7. ALTERATIONS

Rear addition; side wing (attached garages); wrap around porch added later.

8. NOTABLE FEATURES

Frieze; rectangular gable window; 6/6 sash.

9. ARCHITECTURAL-HISTORICAL

A simple porch on two sides of this house helps integrate later additions and gives this small house a substantial appearance. It is a good example of the simplified Greek Revival style in Guilford.

Mrs. Rachel Goldsmith is identified as the owner of this property on the 1852 map - Rachel Leete Goldsmith was the wife of John Goldsmith III, grandson of John Goldsmith who settled on Moose Hill circa 1751. The property is cited on the 1868 map as owned by Jno C. Goldsmith

10. SOURCES

1852 and 1868 Map; Mary Hoadley Griswold Scrapbook p.65; Steiner.

checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS Clapboard
Wood Shingle ☐ Brick ☐ Stucco ☐ Asbestos Shingle ☐ Other: ☐ Fieldstone ☐ Asphalt Siding ☐ Concrete ☐ Board & Batten ☐ Cut Stone ☐ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: ☐ Masonry ☐ Iron or Steel ☐ Concrete ☐ Other: Post & Beam Balloon 13. **ROOF** a. Pitched

Saltbox Gable-front ☐ Shed ☐ Hip ☐ Other: ☐ Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b.

Tower(s) □ Monitor ☐ Dormered Gable □ Cupola ☐ Dome c. D Wood Shingle Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: LOT SIZE: 1,53 ACRES 14. NUMBER OF STORIES: **APPROXIMATE DIMENSIONS:** 15. CONDITION: Exterior □ Excellent ₩ Good ☐ Fair ☐ Poor ☐ Bad 16. CONDITION: Structure DESCRIPTION ☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad 17. OUTBUILDINGS (visible from public road) ☐ Carriage House ☐ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) E Planted Grounds ☐ Garden □ Terracing ☐ Plaza ☐ Court Stone Wall(s) ☐ Pickett Fence ☐ Iron Fence ☐ Post & Rail ☐ Other: 19. SURROUNDING ENVIRONMENT a.

Town Street b.

Commercial c. Nopen Wooded Rural ☐ Industrial ☐ Semi-rural Agricultural ☐ Lakefront ☐ Clustered Growth Residential ☐ Coastal □ Development Vacation, now or originally ☐ Salt marsh □ Of supportive value to a supportive value. d.

Of outstanding scenic/architectural value Of supportive value to contiguous scenic/architectural area Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT IX Important □ Supportive ☐ Neutral ☐ Other: 21. OWNERSHIP Private ☐ Public □ Interior accessible D. PENAR Date 7/8/8/ 22. Name BY Photographer D. PENAR Date 7/8/8/ COMPILED Negative ROLL 6:12 Organization: Guilford Preservation Alliance P.O. Box 199, Guilford, Conn. 06437 GLFD'S NEG. 6: 23. THREATS TO BUILDING ONLY ☐ None Known ☐ Highways □ Vandalism □ Developers ☐ Zoning ☐ Other: ☐ Renewal ☐ Private Owner □ Deterioration FOR OFFICE USE 24. SUBSEQUENT EVALUATIONS

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the

In all categories below, check more than one box if applicable.