DENTIFICATION

DESCRIPTION

SIGNIFICANCE

10. sources

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

1. ADDRESS 7 Old Quarry Road (map 18, lot 7)

2. NAME (historic)

Sarah Walker

NAME (comm

(common)

3. USE (historic) USE

(present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



FOR OFFICE USE ONLY

Site No.

IF NR SPECIFY

Potential

Actual

Town No.

DISTRICT

S

NR

QUAD:

5. ARCHITECT

6. DATE

c1888

BUILDER STYLE

Queen Anne

7. ALTERATIONS

Porch missing; door.

8. NOTABLE FEATURES

Overhanging eaves; decorative shingles in the gable; front rectangular bay window; side projection with beveled sides; high stone foundation.

9. ARCHITECTURAL-HISTORICAL

A variety of surface textures and architectural shapes are features that give this house its special interest. One two-story bay with beveled sides is topped by a cross gable and another bay hangs out from the second story on the front. Fancy shingle work and clapboarding make for interesting textures on the sides. Houses of this style usually had fancy porches, and this house seems to be missing its porches. Nonetheless, it is a highlight of its small neighborhood.

Connecticut Historical Commission; Guilford Land Records.

SOURCES

checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS X Clapboard ☐ Brick ☐ Stucco ☐ Asbestos Shingle ☐ Other: ☐ Wood Shingle ☐ Fieldstone ☐ Concrete ☐ Asphalt Siding ☐ Board & Batten ☐ Cut Stone □ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: □ Masonry ☐ Iron or Steel □ Concrete ☐ Other: Post & Beam Balloon 13. **ROOF** a. D Pitched □ Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Saltbox ☑ Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b.

Tower(s) □ Monitor ☐ Cupola ☐ Dormered Gable □ Dome c. D Wood Shingle X Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: 14. NUMBER OF STORIES: **APPROXIMATE DIMENSIONS:** LOT SIZE: 3 ACRE 15. CONDITION: Exterior ☐ Excellent ☐ Good X Fair ☐ Poor □ Bad 16. CONDITION: Structure DESCRIPTION ☐ Excellent ☐ Good □ Poor ☐ Fair □ Bad 17. OUTBUILDINGS (visible from public road) ☐ Carriage House □ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) ☐ Planted Grounds ☐ Garden □ Terracing ☐ Plaza ☐ Court ☐ Stone Wall(s) ☐ Pickett Fence ☐ Iron Fence ☐ Post & Rail ☐ Other: 19. SURROUNDING ENVIRONMENT a. D Town Street b.

Commercial c. D Open ☐ Rural ☐ Industrial ☐ Wooded ☐ Semi-rural ☐ Agricultural □ Lakefront Clustered Growth **2** Residential Coastal □ Development ☐ Vacation, now or originally ☐ Salt marsh d.

Of outstanding scenic/architectural value Of scenic/architectural value Of supportive value to contiguous scenic/architectural area M Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT ☑ Important □ Supportive □ Neutral ☐ Other: 21. OWNERSHIP ☐ Public Private ☐ Interior accessible TUDEX NO. 307 22. Name D. PENAR BY 22: Photographer D. PENAR COMPILED OA Negative Organization: Guilford Preservation Alliance 22: P.O. Box 199, Guilford, Conn. 06437 23. THREATS TO BUILDING OFFICE USE ONLY □ None Known ☐ Highways ☐ Vandalism ☐ Developers □ Zoning ☐ Renewal ☐ Private Owner Deterioration ☐ Other: 24. SUBSEQUENT EVALUATIONS

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the

In all categories below, check more than one box if applicable.

FOR