DENTIFICATION

SOURCES

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

1. ADDRESS

41 Opening Hill Road (map 82, lot 29)

2. NAME

(historic)

William Johnson

NAME

(common)

3. USE

(historic) USE (present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



FOR OFFICE USE ONLY

Site No. 31

Potential

IF NR. SPECIF

Actual

5. ARCHITECT

6. DATE

c1850

BUILDER STYLE

UTM QUAD:

DISTRICT

NR

S

Greek Revival

7. ALTERATIONS Screened porch around the entrance; outside chimney.

8. NOTABLE FEATURES Boxed cornice (pedimented); frieze; rectangular gable window with decorative muntins; 6/6 sash; brick chimney; stone foundation.

9. ARCHITECTURAL-HISTORICAL

The street side of this house presents the regular facade topped by a pedimented gable pierced by a rectangular window that are is common to Guilford's Greek Revival style. However, no door surrounded by the pilasters and entablature of the style is visible on the side facing the road. The entrance faces the driveway. The house is an interesting variation of the Greek Revival plan.

10. SOURCES

1852 Map.

☐ Wood Frame: ☐ Masonry ☐ Iron or Steel ☐ Concrete ☐ Other: Post & Beam Balloon 13. **ROOF** a. Pitched Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Saltbox Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel □ Mansard ☐ Flat ☐ Sawtooth b. D Tower(s) ☐ Monitor ☐ Cupola ☐ Dormered Gable □ Dome c. D Wood Shingle ☐ Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: 14. NUMBER OF STORIES: **APPROXIMATE DIMENSIONS:** LOT SIZE: 5 ac 15. CONDITION: Exterior ☐ Excellent Good ☐ Fair □ Poor □ Bad 16. CONDITION: Structure DESCRIPTION □ Excellent ☐ Good ☐ Fair □ Poor □ Bad 17. OUTBUILDINGS (visible from public road) ☐ Barn(s) ☐ Carriage House Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) Planted Grounds ☐ Garden ☐ Terracing ☐ Plaza ☐ Court ☐ Stone Wall(s) ☐ Pickett Fence ☐ Iron Fence ☐ Post & Rail ☐ Other: 19. SURROUNDING ENVIRONMENT a.

Town Street b.

Commercial c. D Open Rural ☐ Industrial **W**ooded Semi-rural ☐ Agricultural ☐ Lakefront Clustered Growth Residential Coastal ☐ Development Vacation, now or originally Salt marsh d.

Of outstanding scenic/architectural value ☑ Of scenic/architectural value Of supportive value to contiguous scenic/architectural area ☐ Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT ☐ Important □ Supportive □ Neutral Other:

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the

☐ Stucco

□ Concrete

☐ Cobblestone

☐ Renewal 24. SUBSEQUENT EVALUATIONS

21. OWNERSHIP ☐ Public

22. Name

7/15/81 Date

☐ Asbestos Shingle

☐ Asphalt Siding

☐ Aluminum/Vinyl

☐ Other:

Date

Negative R9:31

311

Organization: Guilford Preservation Alliance

Private

P.Odiseos

Photographer P.Odiseos

In all categories below, check more than one box if applicable.

11. MATERIALS Clapboard

12. STRUCTURE

☐ Wood Shingle

☐ Board & Batten

checked box; or, if drawn from a previous investigator, give source.

☐ Brick

☐ Fieldstone

☐ Cut Stone

P.O. Box 199, Guilford, Conn. 06437

Olfds Nog. R9:

23.	THREATS TO BUILDING		
	☐ None Known	Highways	☐ Vandalism
	☐ Renewal	Private Owner	☐ Deteriorat

□ Deterioration

□ Interior accessible

□ Developers ☐ Other:

□ Zoning