

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No. 3
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 909 Beaver Head
(map 116, lot 2)
2. NAME
(historic) General Augustus Collins
NAME
(common)
3. USE
(historic)
USE
(present) Private House
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1788 written on chimney BUILDER
STYLE Colonial
7. ALTERATIONS The Greek Revival door on the Colonial facade evidently indicates a desire on the part of a later owner, probably around 1840, to keep up with the times. First floor windows on facade a modern alteration. Sash of other windows altered at various times. Later additions to rear. Aluminum ~~stone~~ sash.
8. NOTABLE FEATURES ^{STORM}
The very slight overhang on front and sides with its row of dentils all across the facade (and also over the door) is curious: are the dentils perhaps a later embellishment? Chimney appears to be original.

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL The Connecticut Historical Commission survey of 1972 comments: "It is suspected by local historians that this house is actually earlier than the date of 1788 on the chimney, because of the 1-room depth and shallow overhang. Chimney seems to be of appropriate size."
General Augustus Collins served in the Revolutionary army. He was a prominent public man, a magistrate for many years and served the town in nearly forty sessions of the legislature. His sister, Lorraine, married Governor Oliver Wolcott, one of the signers of the Declaration of Independence. Collins was born in 1743 and died in 1814.

SOURCES

10. SOURCES Tercentenary Committee; Connecticut Historical Commission '72; Colonial Dames; Steiner.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: 198.3' x 321' x 188.67' x 322.1'

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|---|---|--|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input checked="" type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): Corn Crib | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input checked="" type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--|--|---|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input checked="" type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 3

22. Name

P.O. D. Penar

Date 7/2/81

Photographer

P.O. Discos

Date 7/2/81

Negative

Organization:

Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Roll 3: 49

5Hd's Neg. R. 3: 8A

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR	
Town No.:	
UTM	:
QUAD:	
DISTRICT	
<input type="checkbox"/> S	<input type="checkbox"/> NR

ALTERATIONS

Typist's

The Greek Revival door on the Colonial facade evidently indicates a desire on the part of a later owner, probably around 1840, to keep up with the times. First floor windows on facade a modern alteration. Sash of other windows altered at various times. Later additions to rear. Aluminum storm sash.

IDENTIFICATION

1. ADDRESS 909 Beaver Head
(map 116, lot 2)
2. NAME
(historic) General Augustus Collins
NAME
(common)
3. USE
(historic)
USE
(present) Private House
4. IF MOVED, WHEN AND FROM WHERE:

DESCRIPTION

5. ARCHITECT
6. DATE 1788 written on chimney BUILDER STYLE Colonial
7. ALTERATIONS First-floor windows on facade a modern alteration of other windows altered at various times. tions to the rear. Aluminum storm sash. The Greek Rev the Colonial facade evidently indicates a wish to keep
8. NOTABLE FEATURES The very slight overhang on front and si row of dentils all across the facade (an the door) is curious: is it perhaps a later embellishm appears to be original. (are the dentils)

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL The Connecticut Historical Commission 1972 comments: "It is suspected by torians that this house is actually earlier than the date the chimney, because of the 1-room depth and shallow overne y seems to be of appropriate size."
General Augustus Collins served in the Revolutionary army. He was a prominent public man, a magistrate for many years and served the town in nearly forty sessions of the legislature. His sister, Lorraine, married Governor Oliver Wolcott, one of the signers of the Declaration of Independence. He was born in 1743 and died in 1814. (Steiner) Collins

SOURCES

10. SOURCES Date and name: Tercentenary Committee; Other: Connecticut Historical Commission '72; Colonial Dames; Steiner.

See attached slip.