

FOR OFFICE USE ONLY	
Town No.:	Site No 18
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 2955 Boston Post Road
(map 83, lot 5)
2. **NAME**
(historic)
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** Not known **BUILDER**
7. **ALTERATIONS** **STYLE** Vernacular

SIGNIFICANCE

8. **NOTABLE FEATURES**
9. **ARCHITECTURAL-HISTORICAL**
 To a basic house with a basic porch an owner has added a bit of personal fantasy in the form of a pair of vase-shaped windows with curving diamond panes.

SOURCES

10. **SOURCES**

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box, or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: *1 1/2* APPROXIMATE DIMENSIONS: LOT SIZE: *90 acres*

15. CONDITION: Exterior
- Excellent
 - Good
 - Fair
 - Poor
 - Bad

16. CONDITION: Structure
- Excellent
 - Good
 - Fair
 - Poor
 - Bad

17. OUTBUILDINGS (visible from public road)
- Barn(s)
 - Carriage House
 - Garage
 - Shed(s)
 - Shop(s)
 - Other (well, stand, greenhouse, gazebo, privy, etc.): *Warehouse next door*

18. LANDSCAPING (visible from public road)
- Planted Grounds
 - Garden
 - Terracing
 - Plaza
 - Court
 - Stone Wall(s)
 - Pickett Fence
 - Iron Fence
 - Post & Rail
 - Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

Index No. 18

22. Name *D. Penar*
 Photographer *D. Penar*
 Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Date *7/7/81*
 Date *7/7/81* Negative Roll *6:2*

Guilford Neg 6:4

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

More recently the owner of this house was interviewed by Elizabeth Mills Brown and new information was acquired.

Source: Elizabeth Mills Brown MS notes.