

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No. 42
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 159 Boston Street
(map 40, lot 139)
2. NAME
(historic) Charles Caldwell
NAME
(common)
3. USE
(historic)
USE
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1740
- BUILDER
STYLE Colonial and Federal
7. ALTERATIONS
Historians believe the house to have been originally of the central chimney type: see below. Major fire in 1919.
8. NOTABLE FEATURES With its sharply pitched roof and hewn overhangs ornamented with carved corbels at the corners, this house bespeaks its early origin and is one of Guilford's notable survivals. Deep and massive in outline, it must have been one of the more imposing structures of its time. The present twin chimneys probably date from a re-modeling in the Federal period, sometime around 1815, at which time the dainty little porch, fanlight, and windows were presumably also added.

SIGNIFICANCE

"Charles" is not a common name in Puritan New England - for obvious reasons. The explanation in this case is that Charles Caldwell was a Scot, hailing from Perth. He and his brother John are said to have deserted from the British army during the Scottish rebellion led by the Old Pretender and to have come to America about 1718. They were merchants - aristocratic in their ways, we are told, and unaccustomed to the industry of New England. Nevertheless, judging by his fine house, Charles flourished on this new soil. He married Anna, the daughter of the Reverend Thomas Ruggles, and lived here until his death in 1765.

SOURCES

10. SOURCES
Tercentenary Committee; Dorothy Whitfield Society '76; Connecticut Historical Commission '72; Federal Writer's Guide; Steiner; Kelly, Early Domestic Architecture; (cont'd. on next sheet)

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|---|--|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 1/2 ACRE

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input checked="" type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input checked="" type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input checked="" type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 42

22. Name D. PENAR

Date 7/23/81

Photographer D. PENAR

Date 7/23/81

Negative ROLL 20:13A

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 20:14

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

10. SOURCES cont'd.

Isham and Brown; Mary Hoadley Griswold, p. 129-30. Photograph: Charles Hubbard Collection, Guilford Keeping Society. Illustrations at various dates appear in several of the above sources.