

Town No.:

Site No.:

48

UTM

QUAD:

DISTRICT

☐ S☐ NR

IF NR SPECIFY

☐ Actual☐ Potential

State of Connecticut

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

IDENTIFICATION

1. **ADDRESS** 296 Boston Street
(map 48, lot 33)
2. **NAME**
(historic) Edwin Griswold
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** 1870-71 **BUILDER**
STYLE Folk
7. **ALTERATIONS**
Rear addition; aluminum/vinyl siding; aluminum door.

8. **NOTABLE FEATURES**9. **ARCHITECTURAL-HISTORICAL**

Diminutive in size, the facade almost wholly given over to the windows which seem by contrast large and stately, this little house today has great appeal in spite of changes. The bracketed porch with its crisp wooden railing enhances the effect of lightness and daintiness.

Immediately after it was built, the house was conveyed from Edwin Griswold to Samuel Griswold (cost, \$1100). The present owners recently found in the attic Samuel's honorable discharge from the Union Army in the Civil War.

SIGNIFICANCE

10. **SOURCES**

Title search, Mrs. R.W. Gaines.

SOURCES

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. **MATERIALS**

- | | | | | |
|---|-------------------------------------|--------------------------------------|--|---------------------------------|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input checked="" type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. **STRUCTURE**

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. **ROOF**

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched | <input checked="" type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. **NUMBER OF STORIES:**

2

APPROXIMATE DIMENSIONS:

LOT SIZE: 90' X 200'

15. **CONDITION: Exterior**

- | | | | | |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. **CONDITION: Structure**

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. **OUTBUILDINGS** (visible from public road)

- | | | | | |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. **LANDSCAPING** (visible from public road)

- | | | | | |
|---|--|-------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input checked="" type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. **SURROUNDING ENVIRONMENT**

- | | | |
|--|--|---|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input checked="" type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input checked="" type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input checked="" type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. **ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT**

- | | | | | |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input type="checkbox"/> Important | <input checked="" type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|

21. **OWNERSHIP**

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 48

22. **Name** D. PENAR

Date 7/23/81

Photographer D. PENAR

Date 7/23/81

Negative ROLL 18:21A

Organization: Guilford Preservation Alliance

P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 18:22

23. **THREATS TO BUILDING**

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. **SUBSEQUENT EVALUATIONS**

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

Addenda 1983

296 Boston Street

Add to Sources: Guilford Land Records; interview
 Mrs. R. W. Gaines 1982.