

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORM						
Building Name (Commo	on) 394 Boston S	treet				
Building Name (Historic	:)					
Street Address or Locati	on 394 Boston S	Street				
Town/City Guilford	Town/City Guilford Village		County New Haven			
Owner(s) Mary Ann F	ido			Public	X Private	
PROPERTY INFOR	-					
Present Use: Residentia	al: single dwellin	g				
Historic Use: Residenti	al: single dwellir	Ig				
Accessibility to public:	Exterior visible	from public road?	Yes No			
		If yes, explain				
Style of building Coloni	al Revival		Date of	Construction 1947 (He	lander)	
Material(s) (Indicate use		priate):				
Clapboard	Asbestos Siding	g 🛛 Brick	Wood Shing	gle 🛛 Asphalt S	iding	
X Fieldstone	Board & Batten □ Stucco □ Cobblestone □ Aluminum Siding					
Concrete (Type) Cut Stor	ne (Type)		
Structural System						
Wood Frame	Post & Beam	Balloon	X Load bearing	masonry Structu	ral iron or steel	
Other						
Roof (<i>Type</i>)						
🗙 Gable	🗌 Flat	☐ Mansard	Monitor	Sawtooth		
Gambrel	Shed	🗖 Hip	Round	Other		
(Material)						
Wood Shingle	🗌 Roll Asph	alt 🗌 Tin	Slate	🗙 Asphalt Shingle	1	
🗖 Built up	Tile	Other_		_		
Number of Stories: 1		Approximate Dir	nensions <u>30' x 35'</u>			
Structural Condition:	Exce	llent 🔀 Good	🗌 Fair	Deteriorated		
Exterior Condition:	Excel	lent 🛛 Good	🗌 Fair	Deteriorated		
Location Integrity:	On original site	e Moved	When?			
Alterations? Yes	🗙 No 🛛 If	yes, explain:				
FOR OFFICE USE:	Town #	Site #				
	District: S	\square NR \square If NR	, Specify:	ctual Detential		

PROPERTY INFORMATION (CONT'D)

Related outbuilding	s or landscape fea	itures:			
Barn	Shed	🗙 Garage	Carriage House	Shop	Garden
Other lands	cape features or bui	ldings:			
Surrounding Enviro	onment:				
Open land	Woodland	Residential	Commercial	Industrial	Rural
🗙 High buildir	ng density	Scattered build	lings visible from site		
• Interrelationship of	building and surro	undings:			
			de of Boston Street. A hed garage. The garag	•	

the northeast corner. The property is across the street and to the northeast of Alderbrook Cemetery. It is located to the west of the intersection of Soundview Road and Boston Street. (See continuation sheet)

• Other notable features of building or site (Interior and/or Exterior)

This one-story, Colonial Revival cape style dwelling is constructed of field stone and has a side-gable roof. The roof is covered in asphalt shingles. The three-bay facade faces south, and gable-roof dormers with pediments protrude from the slant of the roof. The main entry is centered on the facade and is reached by stone stairs with an iron railing. (See continuation sheet)

Architect ____

Builder _____ Joseph Testori (Helander)

• Historical or Architectural importance:

This dwelling was built by Joseph Testori in 1947. The Testori brothers, Joseph and Isadoro, were stone masons in Guilford. Joseph came to the United States first and built a home on East Creek on Old Boston Street. He later built two more stone houses on Boston Street. Isadoro arrived in the United States after Joseph, and lived with him for some time. Joseph Testori was born in Italy in 1877. In the 1930 United States Federal Census, Joseph Testori is listed as a stone mason living on Leete's Island Road. Living with him is his wife, Olive and his children: Ida, Edward, Betty, and Joseph. According to the census record, Testori immigrated to the United States in 1892 and married Olive c. 1901 at the age of 24. He died in 1957 at the age of 80 and is buried in St. John's Cemetery. (See continuation sheet)

Sources:

Guilford Tax Assessor property records accessed at http://www.propertyrecordcards.com/PropertyResults.aspx? towncode=060&uniqueid=7200 on 11/4/2015. Helander, Joel, Email Correspondance 8/21/2015 and 11/6/2015. Baxter, Linda Trowbridge. "The Newcomers: A Study of Immigrants to Guilford, Connecticut 1850-1930." Dexter, Michigan: Thomson-Shore, Inc., 1985. Ancestry.com. 1930 United States Federal Census of Guilford.

Photographer Kristen Nietering	Date1/17/2015							
View South view of the house, came		Negative on File						
Name Kristen Nietering		Date 11/4/2015						
Organization Guilford Preservation A	lliance							
Address 199 PO Box Guilford, CT 06437								
• Subsequent field evaluations:								
Latitude & Longitude: 41.287558, -72.666213								
Threats to the building or site:								
⊠ None known ☐ Highways	Vandalism	Developers	Renewal	Private				
Deterioration Zoning	Other		Explanation _					



State Historic Preservation Office

HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

394 Boston Street

Interrelationship of building and surroundings

Less than a mile to the west is the Guilford Green. Surrounding the property are nineteenth and twentieth century single-family dwellings.

Other Notable Features

It is protected from the elements by a gable-roof overhang supported by slender posts. The fenestration consists of multi-paned iron stationary windows. A stone chimney runs up the west elevation of the house, and a garage addition was added to the east elevation.

Historical or Architectural importance

In an interview Joel Helander had with Ed Testori (Joseph Testori's son) in 2009, he said this house was built by Joe Testori in 1947. He mentioned that the walls were one foot thick and the floor joists were salvaged railroad or trolley ties. He also believed the house was built with granite (Helander email correspondence). Joseph Testori built two stone buildings at 433 Boston Street, one of the building was built as a garage/apartment.

