Town No.:		Site No. 29						
UTM		1		-	60			1
QUAD:		LARCO LARCO	and i					
DISTRI		2	IF	Actu	SPECIE		Poten	tia

State of Connecticut **CONNECTICUT HISTORICAL COMMISSION** 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

	1. ADDRESS 44 Boston Street (map 40, lot 12)	1 4 4 4 4 A						
CATION	2. NAME (historic) Russell Crampton NAME (common)	A Contraction						
IDENTIFICATION	3. USE (historic) USE (present) Private house							
	(present) Private House 4. IF MOVED, WHEN AND FROM WHERE:	ATTICAL DISTORT						
	844	UII						
	7. ALTERATIONS							
	Extension to rear; aluminum siding and s	a						
DESCRIPTION	8. NOTABLE FEATURES The porch is the only original feature of still be seen. The fluted columns are of design. Note also granite foundation.							
	9. ARCHITECTURAL-HISTORICAL							
1	It is surprising to find a Greek Revival gable end to the side in the Colonial ma But Guilford clung to its old ways for a	in						
SIGNIFICANCE	Prestant & Burdon (1997) Prestant & Burdon (1997) Contrarte (2000, 1997) Contrarte (2000, 1997)							
	and a second disconsistent disconsistent disconsistent disconsistent disconsistent disconsistent disconsistent Anna 1970 disconsistent disconsiste							
CUNCES	10. SOURCES David D. Dudley from William Weld Ledger Society'76.	r .						

BUILDER	Willia	am Weld
STYLE	Greek	Reviva

Dorothy Whitfield

sh.

the house that can a somewhat unusual

house still turning its ner at such a late date. long time.

SOURCES

In all categories below, check more than one box if applicable.

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11	MATERIALS			- 14	
	Clapboard Wood Shingle	Brick Fieldstone	Stucco Concrete	Asbestos Shingle	D Other:
	Board & Batten	Cut Stone		Asphalt Siding	
12	STRUCTURE			Prospect Break, Hain	
12	Wood Frame:	Masonry	Iron or Steel	Concrete	Other:
	 Post & Beam Balloon 		There is the the		
	L Balloon				
	ROOF	564.00			
a	. ₽ Pitched □ Saltbox	Gable-front Cross-gable	Hip Flat Hip	Shed False Dormer	D Other:
	Gambrel	□ Mansard	□ Flat	□ Sawtooth	
b	. D Tower(s)	Monitor	Cupola	Dormered Gable	Dome
с	. D Wood Shingle	Asphalt Shingle	□ Slate sent 8 not	D Metal	D Other:
14), lot 12)	(map 40	
14	NUMBER OF STORIES:	212 APPROXIMA	TE DIMENSIONS:	LOT SIZE:	1/4 ACRE (APPROX)
15	CONDITION: Exterior				(AFFROX)
	Excellent	Good Good	🛱 Fair	Poor	Bad
16	CONDITION: Structure				
	Excellent	Good	Fair	D Poor	Bad
17	OUTBUILDINGS (visible	from public road)	eation	Private	
	D Barn (s)	Carriage House	Garage (INFORED)	□ Shed(s)	□ Shop(s)
	Other (well, stand, green	house, gazebo, privy, etc.	.):		ROM ROM
18	LANDSCAPING (visible f	from public road)			
	 Planted Grounds Stone Wall(s) 	Garden Pickett Fence	Terracing	D Plaza	Court
		LI FICKell Felice	Iron Fence	D Post & Rail	Other: POST PENCE
	SURROUNDING ENVIRO	DNMENT		1844	
a	□ Rural		b. It Commercial		c. Koopen
	Semi-rural		Agricultural		Lakefront
	Clustered Growth	.dase brie and	Residential	nally of correct	Coastal Salt marsh
d	B Of outstanding scenic	architectural value			
	 Of scenic/architectura Of supportive value to 	l value	actural area		
	Neutral	contiguous scenic/archit	ectural area		
	Other:	dt to erutset	Envira tura in Envir	and the set of the second	
20.	ROLE OF BUILDING IN	and and a man a second the	FENVIRONMENT	porch 15 the	901
	D Vital	MImportant	Supportive	Neutral	D Other:
21.	OWNERSHIP				
	D Public	R Private	Interior accessible		
24	imiut ilite ee.	sk Revival hou	to find a Gree	is surprising	ENDEX NO. 29
22	Name D. PENAK	tonnem lermon	a blo ett et em	Date 7/22/8/	-0-50
	Photographer D.P.		a neo cor ob Sta		0110
				Date 7/22/87	Negative ROLL 16:23,
	Organization: Guilfor				
	P.U. B	ox 199, Guilford, Conn	. 06437	CIPD's	11-0 11:01
-		ann an ann an		GLFD'S	NEG 16:24
23	THREATS TO BUILDING				
	None Known Renewed	Highways	□ Vandalism	Developers	Zoning
	Renewal	Private Owner	Deterioration	Other:	
24	SUBSEQUENT EVALUAT				
	ariatum K *91	. Aleroos ple	Porothy Whitii	a Ma	
				isty'?6.	