

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No. 59
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 22 Broad Street  
(map 39, lot 15)
2. NAME Reuben Stone  
(historic)  
NAME  
(common)
3. USE  
(historic)  
USE Private house  
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1769
7. ALTERATIONS In 1842 the roof line was altered making the roof less steep and adding an overhang; also the Greek Revival portico was added; new chimney.
8. NOTABLE FEATURES Overhanging eaves; a very slight overhang on the gable end at the first floor level; Greek Revival portico with fluted columns, wide frieze, and sidelights flank the door.

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL The alteration in the roof of this Colonial house changes the overall look of the house. However, close examination reveals the slight overhang on the gable is evidence of the true age of the house. The Greek Revival portico with its fluted columns is similar to a number of porticos in Guilford known to have been done by William Weld. This house and its immediate neighbors are situated behind a fine series of connecting picket fences.  
Reuben and Caleb Stone, sons of Caleb, inherited shares in the ownership of Faulkner's Island in 1761. They later sold these shares circa 1800. Reuben Stone made two trips to New Haven and one to Hartford to arrange procurement of provisions for Guilford's Revolutionary soldiers. He was reimbursed for this travel on 12 April 1779.

SOURCES

10. SOURCES Tercentenary Committee; Dorothy Whitfield Society '76; Connecticut Historical Commission '72; Colonial Dames. Photograph: Guilford Keeping Society; Guilford Library.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |   |                                     |                                      |   |                                 |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle         | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten       | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |   |  |                                   |   |                                 |
|---|--|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched      | <input type="checkbox"/> Gable-front     | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox                    | <input type="checkbox"/> Cross-gable     | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel                    | <input type="checkbox"/> Mansard         | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)                | <input type="checkbox"/> Monitor         | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 2.75 ACRES (APPROX)

15. CONDITION: Exterior

- |                                    |  |                               |                               |                              |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |  |                                  |                                  |
|---|---|--|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s)                      | <input type="checkbox"/> Carriage House | <input checked="" type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   |  |                                  |                                  |

18. LANDSCAPING (visible from public road)

- |  |   |                                     |                                      |                                 |
|--|---|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden                   | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)   | <input checked="" type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street                                   | b. <input type="checkbox"/> Commercial               | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial                  | <input type="checkbox"/> Wooded             |
| <input type="checkbox"/> Semi-rural  | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth  | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value     |  |   |
| <input type="checkbox"/> Of scenic/architectural value                               |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |   |                                    |                                     |                                  |                                 |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 59

22. Name D. PENAR

Date 7/21/81

Photographer D. PENAR

Date 7/21/81

Negative ROLL 14:30A

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD's NEG 14:30

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

Sources: Steiner; Dana Collection.