

FOR OFFICE USE ONLY	
Town No.:	Site No.: 84
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

- ADDRESS** 102 Church Street
(map 46, lot 23)
- NAME**
(historic) George Weld
NAME
(common)
- USE**
(historic)
USE
(present) Private house
- IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

- ARCHITECT**
- DATE** c1848 **BUILDER**
STYLE Greek Revival

7. ALTERATIONS
 Siding; side screened porch; south side addition; closed sidelights.

8. NOTABLE FEATURES
 Full pedimented cornice, original rectangular gable window. Portico with entablature, dentils fluted columns, original paneled door.

9. ARCHITECTURAL-HISTORICAL
 This house was built for George Weld, the brother of William Weld, the builder. It is not known exactly what role William may have had in its construction, but one must note the great similarity between this house and the John Seward house at 58 East River Road, which we know was built by William Weld. The house lends its strong residential presence to any area that is becoming increasingly commercial.

SIGNIFICANCE

- SOURCES**
 Dorothy Whitfield Society '76; David D. Dudley, notes. Photograph: Guilford Library.

SOURCES

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:

- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome

- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE:

approx: 160' x 100'

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Stone Wall(s)
- Garden
- Pickett Fence
- Terracing
- Iron Fence
- Plaza
- Post & Rail
- Court
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 84

22. Name P. Odiseos

Date 7/6/81

Photographer P. Odiseos

Date 7/6/81

Negative P-05-22A

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Glfd's Neg. R: 5: 21A

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY