

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY			
Town No.:	Site No. 80		
UTM	:	:	:
QUAD:			
DISTRICT	IF NR SPECIFY		
<input type="checkbox"/> S	<input type="checkbox"/> NR	<input type="checkbox"/> Actual	<input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. ADDRESS 72 Church Street
(map 46, lot 18)
2. NAME Eli Parmelee
(historic)
NAME
(common)
3. USE
(historic)
USE Private house
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1860
- BUILDER
STYLE Greek Revival/Italianate
7. ALTERATIONS
Rear shed roof addition; porch.

SIGNIFICANCE

8. NOTABLE FEATURES
Two story bay window on the side. Porch with posts and brackets; recessed paneled pilasters around original door.
9. ARCHITECTURAL-HISTORICAL
One of several Greek Revival/Italianate houses in the same block of Church Street. All have extremely heavy cornices with strong returns. Several have identical round-top gable windows. The wrap-around porch with its posts and brackets appears to be a later addition.

SOURCES

10. SOURCES
Dorothy Whitfield Society '76; David D. Dudley.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: *2 1/2* APPROXIMATE DIMENSIONS: LOT SIZE: *105 x 225' (approx)*

- 15. CONDITION: Exterior
- Excellent
- Good
- Fair
- Poor
- Bad

- 16. CONDITION: Structure
- Excellent
- Good
- Fair
- Poor
- Bad

- 17. OUTBUILDINGS (visible from public road)
- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.): *Chicken House*

- 18. LANDSCAPING (visible from public road)
- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

- 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT
- Vital
- Important
- Supportive
- Neutral
- Other:

- 21. OWNERSHIP
- Public
- Private
- Interior accessible

Index No 80

22. Name *P. Odiseo* Date *7/7/81*
 Photographer *P. Odiseo* Date *7/7/81* Negative *RS-26A*
 Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Guilford Neg RS-25A

- 23. THREATS TO BUILDING
- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY