

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No.: 99
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. **ADDRESS** 330 Clapboard Hill Road
(map 81, lot 24)
2. **NAME**
(historic) Abraham Dudley
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** 1788 **BUILDER**
STYLE Late Colonial
7. **ALTERATIONS**

8. **NOTABLE FEATURES**
 Overhanging eave, twelve over twelve sash, six over six in gable, doorway with six pane transom, moulding around door.

SIGNIFICANCE

9. **ARCHITECTURAL-HISTORICAL** One of the early Dudley houses on Clapboard Hill. This house has the usual features of a story and a half Colonial house. There is also, however, a high gable window which is unusual. The house has a lean-to at the rear; it is not known whether it is part of the original house.

This house was built by Abraham Dudley who was the brother of Caleb Dudley, III (see 212 Clapboard Hill). Abraham was a weaver who worked with his sons. Their shop was originally located west of the house, later it was moved to the rear of the house.

SOURCES

10. **SOURCES**
 Tercentenary; Dorothy Whitfield Society '76; Connecticut Historical Commission '72; Joel E. Helander, Guilford Long Ago, Vol. II.
 Photograph: Guilford Library.

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

DESCRIPTION

11. MATERIALS

- | | | | | |
|-----------------------------------------------|-------------------------------------|--------------------------------------|-------------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|----------------------------------------|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|-----------------------------------------------------|------------------------------------------|-----------------------------------|-----------------------------------------|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 + 9 arret **APPROXIMATE DIMENSIONS:** **LOT SIZE:** 30 ac

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|------------------------------------------|------------------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|------------------------------------------|------------------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|-------------------------------------------------------|-----------------------------------------|---------------------------------|----------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|-----------------------------------------------------|----------------------------------------|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input checked="" type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--------------------------------------------------------------------------------------|------------------------------------------------------|---------------------------------------------|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input checked="" type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|-------------------------------------------|-----------------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|-------------------------------------------|-----------------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---------------------------------------------|----------------------------------------------|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---------------------------------------------|----------------------------------------------|

INDEX NO. 99

COMPILED BY

22. Name P. Odiseos **Date** 7/14/81
Photographer P. Odiseos **Date** 7/14/81 **Negative R.** 20:25A
Organization: Guilford Preservation Alliance:
 P.O. Box 199, Guilford, Conn. 06437

Gilfd's Neg. R. 20:26

FOR OFFICE USE ONLY

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|----------------------------------------|----------------------------------------|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS