

Town No.:

Site No.:

140

UTM

QUAD:

DISTRICT

IF NR SPECIFY

 S NR Actual Potential

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 4840 Durham Road
 (map 126, lot 4)
2. **NAME**
(historic)
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** c1850 **BUILDER STYLE** Greek Revival
7. **ALTERATIONS**

8. **NOTABLE FEATURES**9. **ARCHITECTURAL-HISTORICAL**

In the shade of huge evergreens, dappled shadows and dark green shutters against white walls make this house a memorable addition to the upper end of the Durham Road. The design, probably of the mid-19th century with various alterations, is not exceptional, but the dramatic siting on a high bank over the road, plus mature landscaping, good maintenance, and the surrounding woodland give the whole property distinction.

This property is identified on the 1852 map as that of one William Parmalee.

SIGNIFICANCE

10. **SOURCES**

Dorothy Whitfield Society '76. 1852 map.

SOURCES

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard *Inferred*
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: **2 1/2** APPROXIMATE DIMENSIONS: LOT SIZE: **2.5ac**

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Stone Wall(s)
- Garden
- Pickett Fence
- Terracing
- Iron Fence
- Plaza
- Post & Rail
- Court
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

22. Name **DP & PO**

Photographer **D.P.**

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Date **July 1 - 1981**
Date **July 1 - 1981** Negative

INDEX NO. 140

ROLL 220

GLFD's NEG 220

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY