FOR OFFI	CE USE ONLY	
Town No.:	Site No. (52	_
UTM		
QUAD:	0.0	
	NR SPECIFY	ential

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: Buildings & Structures

.

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

		- disatenti ()	2011	Service C.	endinate La		
	1. ADDRESS	15 Fair Stree (map 39, lot			Ne. I		
NOL	2. NAME (historic) NAME	Richard Coan	ennensted arater				
IDENTIFICATION	(common)					1 94 m	
NTIF	3. USE (historic)						
D	USE (present)	Private house					
	4. IF MOVED, W	HEN AND FROM WHERE:		NT ASSA			
	5. ARCHITECT	Design of the second	, and a	BUILDER			
	6. DATE	c1841		STYLE I	alian Villa		
	7. ALTERATION	IS	in fields A Christian S Schrift and S				
N							
DESCRIPTION	8. NOTABLE FE False w post in	indow over door	and on the	side; 6/6 sa	ash; wooden l	nitching	
		JRAL-HISTORICAL					
This house resembles several others in the village of Guilford. This house has a portico; several others have full porches while still others have had their porches completely removed. This is one of the carefully maintained nineteenth century houses on the east side of Fair Street. Richard Coan may be the same Richard Coan who bought the Abel Chittenden house on State Street in 1850 and sold it three years later.							
SIGNIFI		iph this					
	proces D						
	10. SOURCES			assoit a	CLASS THREE \$400.0		
SOURCES	Dorothy Mary Ho	Whitfield Soci adley Griswold	ety '76; Cor Yester-Year	mecticut His rs of Guilfor	d, p.53-54	15510n 772.	

1	MATERIALS				
	Clapboard Wood Shingle Board & Batten	 Brick Fieldstone Cut Stone 	Stucco Concrete Cobblestone	□ Asbestos Shingle □ Asphalt Siding □ Aluminum/Vinyl	□ Other:
2.	STRUCTURE U Wood Frame: Post & Beam Balloon	Masonry	Iron or Steel	Concrete	Other:
	ROOF Pitched Saltbox Gambrel	□ Gable-front □ Cross-gable □ Mansard	□ Hip ⊠ Flat Hip □ Flat	□ Shed □ False Dormer □ Sawtooth	Other:
b.	□ Tower(s)	Monitor	Cupola	Dormered Gable	Dome
c.	Wood Shingle	Asphalt Shingle	□ Slate	D Metal	D Other:
4.	NUMBER OF STORIES:	2 APPRON	XIMATE DIMENSIONS:	LOT SIZE:	285'X210'
5	CONDITION: Exterior		Ω.	Richard Cos	noisin
J.	Excellent	Good	□ Fair	Poor	Bad
6	CONDITION: Structure				
	Excellent	Good	Fair	Poor	D Bad
7.	OUTBUILDINGS (visible	from public road)	93	rivate hou	Sau B ·
	Barn(s) Other (well, stand, green)	Carriage House	□ Garage , etc.):	□ Shed(s)	□ Shop(s)
8.	LANDSCAPING (visible f				
	Planted Grounds Stone Wall(s)	□ Garden □ Pickett Fence	□ Terracing □ Iron Fence	Plaza Post & Rail	Court Other:
a.	SURROUNDING ENVIRO	architectural value I value contiguous scenic/au		Baburtaar Bu	c. Salt marsh
0.	ROLE OF BUILDING IN E		TY OF ENVIRONMENT		taou la
	Vital	Important			D Other:
1.	OWNERSHIP	Private	□ Interior accessib	JACINO TOH- MARITON Ne	INDEX NO
2	Name P. Odisc	ossi anedto	Enteren :0013	Date 7/7/81	
C	· · · · · · · · · · · · · · · · · · ·	diseos	no por por energy in the second se	and the second sec	Negeting B 1 1 4
	Organization: Guilford	Con have h	ance	Date 7 7 7 81	Negative [].]: 5
		ox 199, Guilford, C		THE DOUGHT THE	CAOD D
-				51 fd's heq. R	1:5
23.	THREATS TO BUILDING	☐ Highways☐ Private Owner	 Vandalism Deterioration 	□ Developers □ Other:	Zoning
4	SUBSEQUENT EVALUAT	IONS			
	immed feeirote			thy Whitfield So	

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY