-	
_	
_	

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

Town N	0.:	1	186		Site	No.:	15	58	
UTM			1	-		1	!		1
QUAD:		tria			12				
DISTR	ICT		1	IF	NR.	SPECIF	Y		

DESCRIPTION

1. ADDRESS

44 Fair Street (map 39, lot 21)

2. NAME (historic)

Noah Hodgkin, Sr.

NAME

(common)

3. **USE** (historic)

USE (present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



5. ARCHITECT

6. DATE

1762

BUILDER Colonial

Window (2/2); 19th century rear ell; front steps railing; Greek Revival doorway; rebuilt stone chimney.

8. NOTABLE FEATURES

Overhanging eave; boxed cornice with a moulding below.

9. ARCHITECTURAL-HISTORICAL

A good example of 18th century architecture in Guilford and one of Fair Street's remarkable collection of houses. The house was built by Noah Hodgkin, Sr., descendant of John who came to Guilford about 1648, on land purchased in 1761. Following his death in 1783, the property was divided between his widow Hannah, and son, Rev. Beriah Hotchkin, Pastor of the Fourth Congregational Church 1784-(The name Hodgkin became Hotchkin and finally Hotchkiss).

Two other dates have been ascribed to this house; 1742, by the Dorothy Whitfield Society and 1752 by the late owner, Selden Clark, however lack of documentation has led to the use of the

1762 date.

10. SOURCES

Dorothy Whitfield Society; Connecticut Historical Commission; Mary Hoadley Griswold, Yester-Years of Guilford, p. 99; Tercentenary; late owner, Selden Clark interview.

SOURCES

SIGNIFICANCE

24	SUBSEQUENT EVALUA	TIONS			
23.	THREATS TO BUILDING None Known Renewal	G ☐ Highways ☐ Private Owner	☐ Vandalism ☐ Deterioration	□ Developers □ Other:	□ Zoning
(a	P.O. B	ox 199, Guilford, Con	n. 06437	Ifd's Neg. R.1	:10
H C	Organization: Guilfor			Aroperty was alv	sire []
i	Photographer P- 0d	liseos	ni beesdorwe	Date 7/2//8/	Negative R. 1:10
22.	Name P. Odis	tion of house	rkable coller m, 5r., desce	Date 7/21/81	List
	OWNERSHIP Public	☐ Private	☐ Interior accessible	estupa Heroman. M exemple of 18	DUDEX NO:15
	ROLE OF BUILDING IN			□ Neutral	□ Other:
	■ Of outstanding scenic □ Of scenic/architecture □ Of supportive value to □ Neutral □ Other:	al value contiguous scenic/arch	itectural area	is marries	extract a location of the loca
a.	SURROUNDING ENVIRONMENT Town Street Rural Semi-rural Clustered Growth Development	DOMMENT	b. Commercial Industrial Agricultural Residential Vacation, now or o	originally (S\S) wo	c. Open Wooded Lakefront Coastal Salt marsh
	LANDSCAPING (visible to Planted Grounds ☐ Stone Wall(s)	from public road) Garden Pickett Fence	☐ Terracing ☐ Iron Fence	□ Plaza □ Post & Rail	□ Court □ Other:
	OUTBUILDINGS (visible ☐ Barn(s) Other (well, stand, green	☐ Carriage House	☐ Garage c.):	□ Shed(s)	☐ Shop(s)
16.	CONDITION: Structure Excellent	□ Good	□ Fair	□ Poor	□ Bad
	CONDITION: Exterior Excellent	☑ Good.	. ■ Fair	□ Poor	□ Bad
14.	NUMBER OF STORIES:	2 /2 APPROXIM	ATE DIMENSIONS:	LOT SIZE	2 95'X1451
	☐ Wood Shingle	Asphalt Shingle	□ Slate _ 寸991	□ Metal	□ Other:
	■ Saltbox □ Gambrel □ Tower(s)	☐ Cross-gable ☐ Mansard ☐ Monitor	☐ Flat Hip☐ Flat☐ Cupola	☐ False Dormer ☐ Sawtooth ☐ Dormered Gable	□ Dome
a.	ROOF Pitched	☐ Gable-front	O YTHUOD KHAR	□ Shed _	Other:
	STRUCTURE Wood Frame: Post & Beam Balloon	☐ Masonry	☐ Iron or Steel	□ Concrete	□ Other:
	☐ Wood Shingle ☐ Board & Batten	☐ Fieldstone ☐ Cut Stone	☐ Concrete ☐ Cobblestone	☐ Asphalt Siding ☐ Aluminum/Vinyl	

In all categories below, check more than one box if applicable.