

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No.: 171
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 90 Fair Street
(map 46, lot 37)
2. NAME
(historic) Wm. Griffing, Russell, or
NAME D. Redfield
(common)
3. USE
(historic)
USE Private house
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1833 BUILDER
STYLE Federal
7. ALTERATIONS
Wrap around porch; beveled sided "wing" on the south side; windows rectangular bay on the north side (alteration c1900).
8. NOTABLE FEATURES
Fanlight; cut glass side window (c1900); full pediment.

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL

This three-bay Federal house has undergone early alterations, yet the front facade still retains most of its original character. An elliptical window, which appears to have its original glass and muntins is placed in a full pedimented gable.

Three names--William Griffing, Russell, or D. Redfield--have been identified as among the original owners of this property.

SOURCES

10. SOURCES

Dorothy Whitfield Society '76; Mary Hoadley Griswold p. 40, 102.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. **MATERIALS**

- | | | | | |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. **STRUCTURE**

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. **ROOF**

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input checked="" type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input checked="" type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. **NUMBER OF STORIES:**

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: $\approx 70' \times 160'$

15. **CONDITION: Exterior**

- | | | | | |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. **CONDITION: Structure**

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. **OUTBUILDINGS** (visible from public road)

- | | | | | |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. **LANDSCAPING** (visible from public road)

- | | | | | |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. **SURROUNDING ENVIRONMENT**

- | | | |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. **ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT**

- | | | | | |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. **OWNERSHIP**

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 171

22. **Name**

P. Odiseos

Date 7/23/81

Photographer

P. Odiseos

Date 7/23/81

Negative R.1:25

Organization:

Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Glfd's Neg. R.1:25

23. **THREATS TO BUILDING**

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. **SUBSEQUENT EVALUATIONS**

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY