

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No. 180
UTM	:
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. ADDRESS 135 Goose Lane
(map 75, lot 11)
2. NAME
(historic) William Dudley
NAME
(common)
3. USE
(historic)
USE
(present) Doctor's offices
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1806 BUILDER
STYLE Federal
7. ALTERATIONS
Addition to the rear; fenestration altered on the side.

SIGNIFICANCE

8. NOTABLE FEATURES
Slightly overhanging eaves with a moulding below; 6/6 sash; doorway with a six pane transom, and an architrave trim above the transom; field stone foundation.
9. ARCHITECTURAL-HISTORICAL
This is a well-proportioned house of the Federal period. The central doorway has an interesting treatment with a transom surmounted by architrave trim suggesting capitals. A very similar doorway is found at 246 Goose Lane. A stone embankment and picket fence surround a lawn that makes a fine setting for one of Guilford's smaller houses of the Federal period.
William Dudley, one of the sons of Amos Dudley the builder, built this house. Deacon Richard Bartlett once lived here as did Ayres Stevens, a basketmaker

SOURCES

10. SOURCES
Tercentenary Committee; Dorothy Whitfield Society '76; Joel E. Helander, Guilford Long Ago, Vol. II. Photograph: Charles Hubbard Collection.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES:

1 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE:

92 AC

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Stone Wall(s)
- Garden
- Pickett Fence
- Terracing
- Iron Fence
- Plaza
- Post & Rail
- Court
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

Index No 180

22. Name

P. Odiseos

Date 7/14/81

Photographer

P. Odiseos

Date 7/14/81

Negative R919

Organization:

Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Glfd's Neg R. 9-3A

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY