

FOR OFFICE USE ONLY	
Town No.:	Site No.: 183
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

IDENTIFICATION

1. ADDRESS 749 Goose Lane  
(map 81, lot 20)
2. NAME  
(historic) George Dibble  
NAME  
(common)
3. USE  
(historic)  
USE  
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1842 BUILDER STYLE Greek Revival
7. ALTERATIONS  
Siding; 2/2 sash; outside chimney.

SIGNIFICANCE

8. NOTABLE FEATURES  
Boxed cornice with returns; rectangular gable window; doorway with pilasters; entablature and sidelights.
9. ARCHITECTURAL-HISTORICAL  
The irregular window placement of this house is most unusual for houses of its style. The house has a wide doorway with sidelights, pilasters, and an entablature with dentils. George A. Dibble was the first owner of this house built on the site of an earlier house belonging to his grandmother Mindwell Stone Dibble.

SOURCES

10. SOURCES  
Joel E. Helander; Guilford Land Records; Dorothy Whitfield Society '76.

In all categories below, check more than one box if applicable.  
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

**11. MATERIALS**

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

**12. STRUCTURE**

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

**13. ROOF**

- a.  Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b.  Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c.  Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

**14. NUMBER OF STORIES:** *2 1/2*      **APPROXIMATE DIMENSIONS:**      **LOT SIZE:** *3.9 ACRES*

**15. CONDITION: Exterior**

- Excellent
- Good
- Fair
- Poor
- Bad

**16. CONDITION: Structure**

- Excellent
- Good
- Fair
- Poor
- Bad

**17. OUTBUILDINGS (visible from public road)**

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.): *Corn Crib*

**18. LANDSCAPING (visible from public road)**

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

**19. SURROUNDING ENVIRONMENT**

- a.  Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b.  Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c.  Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d.  Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

**20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT**

- Vital
- Important
- Supportive
- Neutral
- Other:

**21. OWNERSHIP**

- Public
- Private
- Interior accessible

*INDEX NO. 183*

**22. Name** *P. O. disos*      Date *7/13/81*  
**Photographer** *P. O. disos*      Date *7/13/81*      Negative *R7:34*  
**Organization:** Guilford Preservation Alliance  
 P.O. Box 199, Guilford, Conn. 06437

*Glfd's Neg. R.7:35*

**23. THREATS TO BUILDING**

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

**24. SUBSEQUENT EVALUATIONS**

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY