

FOR OFFICE USE ONLY	
Town No.:	Site No.: 192
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 35 Graves Avenue
(map 40, lot 35)
2. **NAME**
(historic) C. R. Whedon
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house, apartment
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** 1851 **BUILDER STYLE** Greek Revival
7. **ALTERATIONS**
 Siding; front-side porch (Late Victorian).
8. **NOTABLE FEATURES**
 Full pediment; frieze; rectangular gable window; Greek Revival doorway with plain pilasters and a wide entablature; sidelights.
9. **ARCHITECTURAL-HISTORICAL**
 A full pediment and a broad doorway with sidelights are typical of the Greek Revival in Guilford. The lacy trim on the side porch is a light counterpoint to the solidity of the house's mass.

SIGNIFICANCE

SOURCES

10. **SOURCES**
 Dorothy Whitfield Society '76; 1852 Irvine Map; Guilford Land Records.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: approx. 1/2 acre +

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 192

22. Name P. Odiseos

Date 7/21/81

Photographer P. Odiseos

Date 7/21/81

Negative Roll 13:23

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Old's Neg. Roll 13:23

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY