

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No. 199
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 57 Graves Avenue
(map 40, lot 31)
2. **NAME**
(historic) James R. Dowd
NAME
(common)
3. **USE**
(historic)
USE
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** c1898 **BUILDER STYLE** Queen Anne/Vernacular
7. **ALTERATIONS**
Siding.

SIGNIFICANCE

8. **NOTABLE FEATURES**
Overhanging eaves with small rafters visible; large modestly decorative porch that wraps around three sides of the house; brick foundation.
9. **ARCHITECTURAL-HISTORICAL**
The wrap around porch on this simple, two story, cross-gable house is its most outstanding feature. The porch extends around three sides of the house. Turned posts separate a railing of scroll work and straight boards. James R. Dowd served as a Private in the 27th Regiment during the Rebellion.

SOURCES

10. **SOURCES**
Guilford Land Records; Steiner; 1901 Map

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: approx. 1/4 acre

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 199

22. Name P. Odiseos
 Photographer P. Odiseos
 Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Date 7/22/81
 Date 7/22/81 Negative Roll 13:31

Glfd's Neg. Roll 13:31

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY