

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No.: 204
UTM	
QUAD:	
DISTRICT	
<input type="checkbox"/> S	<input type="checkbox"/> NR
IF NR SPECIFY	
<input type="checkbox"/> Actual	<input type="checkbox"/> Potential

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

IDENTIFICATION

1. **ADDRESS** 372 Great Hill Road  
(map 113, lot 6)
2. **NAME**  
(historic) Warren Linquist  
**NAME**  
(common)
3. **USE**  
(historic)  
**USE**  
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** 1910 **BUILDER**  
**STYLE** Bungalow
7. **ALTERATIONS**  
Some changes c1975.
8. **NOTABLE FEATURES**  
Wide overhanging eaves; dormers in front and rear; round column porch; cobblestone like foundation.

SIGNIFICANCE

9. **ARCHITECTURAL-HISTORICAL**  
The house was built by Lindquist, its first owner.  
There are very few bungalow style houses in Guilford.  
This is a good example and well sited on its land.

SOURCES

10. **SOURCES**  
Interview with Ingela H. Semels (owner 1981).

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a.  Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b.  Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c.  Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 1 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 1.38 acres

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a.  Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b.  Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c.  Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d.  Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 204

22. Name

PO. D. Penar

Date 7/1/81

Photographer

Podiseos

Date 7/1/81

Negative

Organization:

Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

Roll 3: 4

GHF's Neg. R.3: 3A

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY