

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

| FOR OFFICE USE ONLY | |
|--|--|
| Town No.: | Site No. <u>205</u> |
| UTM | |
| QUAD: | |
| DISTRICT | IF NR SPECIFY |
| <input type="checkbox"/> S <input type="checkbox"/> NR | <input type="checkbox"/> Actual <input type="checkbox"/> Potential |

IDENTIFICATION

1. ADDRESS 405 Great Hill Road
(map 113, lot 20)
2. NAME
(historic) Austin Fowler
NAME
(common)
3. USE
(historic)
USE
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE pre-1852
- BUILDER
STYLE Greek Revival--see below
7. ALTERATIONS
Side shed addition; side porch.

8. NOTABLE FEATURES

Wide overhanging eaves; boxed cornice; 6/6 sash; Doric doorway with an entablature, pilasters and sidelights.

9. ARCHITECTURAL-HISTORICAL

Architecturally a puzzling building: Late Colonial in outline with a Greek Revival door. This in itself would not be unusual for c1850 in Guilford where the basic Colonial tradition hung on far into the 19th century and was often combined with Greek Revival ornament and details. But here the height of the stories and the big barnlike roof with untrimmed edges seem far removed from the earlier work. Possibly the roof has been rebuilt. All that we know is that a house is shown on this site on a map of 1852.

SIGNIFICANCE

10. SOURCES Dorothy Whitfield Society '76.

SOURCES

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE:

43' AC.

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|---|---|---------------------------------|---|----------------------------------|
| <input checked="" type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input checked="" type="checkbox"/> Shed(s) 2 | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--|--|---|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input checked="" type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input checked="" type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input checked="" type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 205

22. Name D Remy PO

Date 7/1/81

Photographer Podisco

Date 7/1/81

Negative R3:3

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

glfd's Neg. R3:2A

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

Add to Sources: 1852 Irvine Map.