

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No.: 207
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

IDENTIFICATION

1. ADDRESS 465 Great Hill Road  
(map 113, lot 18)
2. NAME  
(historic) Jonathan Bartlett  
NAME  
(common)
3. USE  
(historic)  
USE  
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1850 BUILDER STYLE Greek Revival
7. ALTERATIONS  
Side addition; garage; porch.

SIGNIFICANCE

8. NOTABLE FEATURES  
Boxed cornice (pedimented); frieze; 6/6 sash; rectangular gable window.
9. ARCHITECTURAL-HISTORICAL  
The very narrow width and asymmetrical facade of this house are striking features. There was no place for the regularity usually found in Greek Revival houses on this diminutive frame. This is an interesting example of the smaller 19th century houses of North Guilford.

SOURCES

10. SOURCES  
1852 Map.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a.  Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b.  Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c.  Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 3.49 ACRES

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a.  Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b.  Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c.  Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d.  Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 207

22. Name P.O. DP

Date 7/1/81

Photographer DP

Date 7/1/81

Negative ROLL 2:35

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD<sup>6</sup> NEG 2:35

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

Sources: Dorothy Whitfield Society.