

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No.: 220
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 40 High Street  
(map 33, lot 79)
2. NAME  
(historic)  
NAME  
(common)
3. USE  
(historic)  
USE  
(present) Private house, apartment  
units
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE Probably c1902
7. ALTERATIONS  
Aluminum windows; enclosed porch.
8. NOTABLE FEATURES  
Jerkinhead roof line; boxed cornice with modified returns; frieze;  
rectangular window in the gable with decorative leaded glass.

**BUILDER**  
**STYLE** Shingle style

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL

The jerkinhead roof appears on several houses in Guilford. This nicely proportioned house is in keeping with the scale of its neighborhood. Although the porch has been enclosed, changing the overall look of the facade, the leaded glass window has been retained as a reminder of the original appearance of the house. A title search has proven inconclusive on this house, appearance points to a date in the early 20th century.

SOURCES

10. SOURCES  
Guilford Land Records.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |  |                                     |                                      |   |                                 |
|--|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input type="checkbox"/> Clapboard               | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten          | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |  |   |                                   |   |                                 |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched      | <input type="checkbox"/> Gable-front                | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox         | <input checked="" type="checkbox"/> Cross-gable     | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel         | <input type="checkbox"/> Mansard                    | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)     | <input type="checkbox"/> Monitor                    | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

2

APPROXIMATE DIMENSIONS:

LOT SIZE: 55' X 205'  
(APPROX)

15. CONDITION: Exterior

- |                                    |                               |  |                               |                              |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |   |                                  |                                  |
|---|---|---|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s)                      | <input type="checkbox"/> Carriage House | <input checked="" type="checkbox"/> Garage APT. | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   | (INFERRED)                                      |                                  |                                  |

18. LANDSCAPING (visible from public road)

- |  |  |                                     |                                      |                                 |
|--|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input checked="" type="checkbox"/> Garden | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)   | <input type="checkbox"/> Pickett Fence     | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |   |  |   |
|---|--|---|
| a. <input checked="" type="checkbox"/> Town Street  | b. <input type="checkbox"/> Commercial               | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural  | <input type="checkbox"/> Industrial                  | <input type="checkbox"/> Wooded             |
| <input type="checkbox"/> Semi-rural   | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth   | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development  | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value                           |  |   |
| <input type="checkbox"/> Of scenic/architectural value  |  |   |
| <input checked="" type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral  |  |   |
| <input type="checkbox"/> Other:   |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |                                |   |                                     |                                  |                                 |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 220

22. Name D. PENAR

Date 7/27/81

Photographer D. PENAR

Date 7/27/81

Negative ROLL 19:8

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 19:8

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS

Sources: Correction: Sanborn map of 1925 (not 1889).