

FOR OFFICE USE ONLY	
Town No.:	Site No.: 221
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

- 1. **ADDRESS** 51 High Street
(map 32, lot 59)
- 2. **NAME** H. Stannard
(historic)
NAME
(common)
- 3. **USE**
(historic)
USE Private house
(present)
- 4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

- 5. **ARCHITECT**
- 6. **DATE** 1873 **BUILDER STYLE** Greek Revival
- 7. **ALTERATIONS**
Siding; porch may be a later addition.

SIGNIFICANCE

- 8. **NOTABLE FEATURES**
Boxed cornice with returns; rectangular gable window; 6/6 sash original; front door.
- 9. **ARCHITECTURAL-HISTORICAL**
A broad frieze emphasizes the eaves and cornice returns of this house, making the roofline an important feature of the house. This house is set off by a picket fence.

SOURCES

- 10. **SOURCES**
Dorothy Whitfield Society '76.

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|--|-------------------------------------|--------------------------------------|--|---------------------------------|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input checked="" type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 **APPROXIMATE DIMENSIONS:** **LOT SIZE:** 65' x 190' (APPROX)

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|----------------------------------|--|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input checked="" type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
|----------------------------------|--|---------------------------------|----------------------------------|----------------------------------|
- Other (well, stand, greenhouse, gazebo, privy, etc.):

18. LANDSCAPING (visible from public road)

- | | | | | |
|---|---|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input checked="" type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input checked="" type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | | | | | | | | | | | | | |
|---|--|---|---|--------------------------------------|--|--|---------------------------------------|---|--|---|---------------------------------|------------------------------------|----------------------------------|-------------------------------------|
| a. <input checked="" type="checkbox"/> Town Street | <input type="checkbox"/> Rural | <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Clustered Growth | <input type="checkbox"/> Development | b. <input type="checkbox"/> Commercial | <input checked="" type="checkbox"/> Industrial | <input type="checkbox"/> Agricultural | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Vacation, now or originally | c. <input checked="" type="checkbox"/> Open | <input type="checkbox"/> Wooded | <input type="checkbox"/> Lakefront | <input type="checkbox"/> Coastal | <input type="checkbox"/> Salt marsh |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value | <input type="checkbox"/> Of scenic/architectural value | <input checked="" type="checkbox"/> Of supportive value to contiguous scenic/architectural area | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: | | | | | | | | | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 221

22. Name D. PENAR

Date 7/27/81

Photographer D. PENAR

Date 7/27/81

Negative ROLL 19:11

Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

GLEED'S NEG. 19:11

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY

Sources: 1889 Sanborn Map.