

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

FOR OFFICE USE ONLY	
Town No.:	Site No. 244
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

IDENTIFICATION

1. ADDRESS 992 Little Meadow Road
(map 91, lot 36)
2. NAME
(historic) S. Davis
NAME
(common)
3. USE
(historic)
USE Private house
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1850 BUILDER STYLE Vernacular
7. ALTERATIONS Window sash; addition to the side wing (closed in area probably was a porch originally).
8. NOTABLE FEATURES Boxed cornice; wide frieze; slightly arched window in the gable.
9. ARCHITECTURAL-HISTORICAL The narrow width of its two perpendicular wings give this house a very tall appearance. With its barns and treed lot, it plays a good role in supporting the rural character of its district.

SIGNIFICANCE

SOURCES

10. SOURCES Dorothy Whitfield Society; 1852 Irvine Map.

In all categories below, check more than one box if applicable.
 If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- Clapboard
- Wood Shingle
- Board & Batten
- Brick
- Fieldstone
- Cut Stone
- Stucco
- Concrete
- Cobblestone
- Asbestos Shingle
- Asphalt Siding
- Aluminum/Vinyl
- Other:

12. STRUCTURE

- Wood Frame:
- Post & Beam
- Balloon
- Masonry
- Iron or Steel
- Concrete
- Other:

13. ROOF

- a. Pitched
- Saltbox
- Gambrel
- Gable-front
- Cross-gable
- Mansard
- Hip
- Flat Hip
- Flat
- Shed
- False Dormer
- Sawtooth
- Other:
- b. Tower(s)
- Monitor
- Cupola
- Dormered Gable
- Dome
- c. Wood Shingle
- Asphalt Shingle
- Slate
- Metal
- Other:

14. NUMBER OF STORIES: 2 1/2 **APPROXIMATE DIMENSIONS:** **LOT SIZE:** 9.29

15. CONDITION: Exterior

- Excellent
- Good
- Fair
- Poor
- Bad

16. CONDITION: Structure

- Excellent
- Good
- Fair
- Poor
- Bad

17. OUTBUILDINGS (visible from public road)

- Barn(s)
- Carriage House
- Garage
- Shed(s)
- Shop(s)
- Other (well, stand, greenhouse, gazebo, privy, etc.): can crib

18. LANDSCAPING (visible from public road)

- Planted Grounds
- Garden
- Terracing
- Plaza
- Court
- Stone Wall(s)
- Pickett Fence
- Iron Fence
- Post & Rail
- Other:

19. SURROUNDING ENVIRONMENT

- a. Town Street
- Rural
- Semi-rural
- Clustered Growth
- Development
- b. Commercial
- Industrial
- Agricultural
- Residential
- Vacation, now or originally
- c. Open
- Wooded
- Lakefront
- Coastal
- Salt marsh
- d. Of outstanding scenic/architectural value
- Of scenic/architectural value
- Of supportive value to contiguous scenic/architectural area
- Neutral
- Other:

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- Vital
- Important
- Supportive
- Neutral
- Other:

21. OWNERSHIP

- Public
- Private
- Interior accessible

INDEX NO. 244

22. Name Podiseos

Photographer Podiseos

Organization: Guilford Preservation Alliance
 P.O. Box 199, Guilford, Conn. 06437

Date 7/7/81

Date 7/7/81

Negative ROLL 20:28A

Glfd's Neg. R 20:29

23. THREATS TO BUILDING

- None Known
- Renewal
- Highways
- Private Owner
- Vandalism
- Deterioration
- Developers
- Other:
- Zoning

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY