

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No. 256				
UTM									
QUAD:									
DISTRICT					IF NR. SPECIFY				
<input type="checkbox"/> S	<input type="checkbox"/> NR	<input type="checkbox"/>	<input type="checkbox"/> Actual	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Potential

IDENTIFICATION

1. **ADDRESS** 2479 Long Hill Road  
(map 101, lot 18)
2. **NAME**  
(historic) Possibly Stephen Fowler  
**NAME**  
(common)
3. **USE**  
(historic)  
**USE**  
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** Probably c 1835
- BUILDER**  
**STYLE** Federal
7. **ALTERATIONS**  
Side bay windows.
8. **NOTABLE FEATURES** Pedimented cornice; mutules and guttae decorate the eaves and raking; curved fanlight in the gable; 12/12 sash; doorway with thin tapered pilasters, bosses, mutules and guttae and a four pane transom; dressed granite block foundation (no mortar used).

SIGNIFICANCE

9. **ARCHITECTURAL-HISTORICAL**  
 The trim along the eaves and gable of this house as well as its doorway are elements of the style of the Federal period. Its placement with its gable end toward the street is more typical of the later Greek Revival. The combination of features make it an interesting example of stylistic transition.

SOURCES

10. **SOURCES**  
 Dorothy Whitfield Society; 1852 Irvine Map. Photograph: Dana p. 47 #64.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |   |                                     |                                      |   |                                 |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle         | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten       | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |   |   |                                   |   |                                 |
|---|---|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched                 | <input checked="" type="checkbox"/> Gable-front | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox                    | <input type="checkbox"/> Cross-gable            | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel                    | <input type="checkbox"/> Mansard                | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)                | <input type="checkbox"/> Monitor                | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Shingle        | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE:

1.54 AC.

15. CONDITION: Exterior

- |                                    |                               |  |                               |                              |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |                                 |   |                                  |
|---|---|---------------------------------|---|----------------------------------|
| <input checked="" type="checkbox"/> Barn(s)           | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input checked="" type="checkbox"/> Shed(s) 1 | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   | WELL                            | 1 GARAGE                                      |                                  |

18. LANDSCAPING (visible from public road)

- |  |  |                                     |                                      |                                 |
|--|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden        | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)   | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input type="checkbox"/> Town Street  | b. <input type="checkbox"/> Commercial               | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial                  | <input checked="" type="checkbox"/> Wooded  |
| <input checked="" type="checkbox"/> Semi-rural                                       | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth  | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value                |  |   |
| <input checked="" type="checkbox"/> Of scenic/architectural value                    |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |                                |   |                                     |                                  |                                 |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 256

22. Name D. PENAR

Date 7/6/81

Photographer D. PENAR

Date 7/6/81

Negative ROLL 4:3

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 4:7A

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY