Z
NOI
4
CA
正
-
Z
E
0

DESCRIPTION

SIGNIFICANCE

SOURCES

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:

Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437

June-December 1981

1. ADDRESS

2548 Long Hill Road (map 100, lot 24)

2. NAME

William Dudley

(historic) NAME

(common)

3. USE

(historic) USE

(present)

Private house

4. IF MOVED, WHEN AND FROM WHERE:



FOR OFFICE USE ONLY

Site No

IF NR SPECIE

Actual

Potential

Town No .:

S

NR

UTM QUAD:

5. ARCHITECT

6. DATE

c 1825

BUILDER STYLE

Federal

7. ALTERATIONS

Shingle siding; rear shed roof addition.

8. NOTABLE FEATURES

Boxed cornice (pedimented); freize; elliptical fanlight with a keystone trim; 6/6 sash; crown mouldings over the windows; recessed doorway with pilasters; entablature; sidelights and a decorative door frame: stone block foundation.
9. ARCHITECTURAL-HISTORICAL

Guilford has few houses with fanlighted gable ends facing the street. Long Hill Road has two closely related houses, this one and no. 2734. In addition to the distinctive fanlight in its pedimented gable, this house has a doorway in which pilasters and an entablature form a reces for a door with a decorative frame and sidelights. It faces the Stephen Fowler house across the street.

William Cornwell Dudley, original owner, born 14 September 1803, was Justice of the Peace at North Guilford 1846. He died in 1888.

10. SOURCES

Dorothy Whitfield Society; 1852 Irvine Map; Connecticut Historical Commission.

Wood Shingle ☐ Fieldstone ☐ Concrete ☐ Asphalt Siding ☐ Board & Batten ☐ Cut Stone ☐ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: ☐ Masonry ☐ Iron or Steel ☐ Concrete Other: Post & Beam Balloon 13. **ROOF** a. Pitched Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Flat Hip ☐ Saltbox ☐ Cross-gable ☐ False Dormer ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b. D Tower(s) ☐ Monitor ☐ Dormered Gable ☐ Cupola □ Dome c. D Wood Shingle Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: 14. NUMBER OF STORIES: APPROXIMATE DIMENSIONS: LOT SIZE: 165/X 243.51 15. CONDITION: Exterior ☐ Excellent Good ☐ Fair □ Poor ☐ Bad 16. CONDITION: Structure DESCRIPTION ☐ Excellent ☐ Fair ☐ Poor ☐ Bad 17. OUTBUILDINGS (visible from public road) ☐ Barn(s) ☐ Carriage House ☐ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) Planted Grounds ☐ Garden ☐ Plaza □ Terracing ☐ Court ☐ Stone Wall(s) ☐ Pickett Fence ☐ Post & Rail ☐ Iron Fence ☐ Other: 19. SURROUNDING ENVIRONMENT a.

Town Street b.

Commercial c. 🗗 Open ☐ Rural ☐ Industrial ☐ Wooded ❷ Semi-rural ☐ Agricultural ☐ Lakefront ☐ Clustered Growth Residential ☐ Coastal ☐ Development Vacation, now or originally ☐ Salt marsh d.

Of outstanding scenic/architectural value Of scenic/architectural value ☐ Of supportive value to contiguous scenic/architectural area ☐ Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT ☐ Vital Important ☐ Supportive 21. OWNERSHIP ☐ Public Private □ Interior accessible DUDEX Date Date Photographer Organization: Guilford Preservation Alliance

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the

☐ Stucco

☐ Asbestos Shingle

☐ Other:

In all categories below, check more than one box if applicable.

11. MATERIALS ☐ Clapboard

checked box; or, if drawn from a previous investigator, give source.

☐ Brick

BY COMPILED

FOR OFFICE USE ONLY

24. SUBSEQUENT EVALUATIONS

23. THREATS TO BUILDING

☐ None Known

☐ Renewal

☐ Vandalism

P.O. Box 199, Guilford, Conn. 06437

☐ Highways

☐ Private Owner

□ Deterioration

☐ Developers Other:

□ Zoning

Indicates that William M. Dudley Ived at 2548 Long Hill Road, North GailFord

Talcott Genealogy - pg. 352

William Miles Dudley 5.1804 - owner garmen Sunder m. Mary Chitterder, 1835

House may be circa 1835. V

Charhof Title in land record would need to be searched.

Kimberly Welch - 3-1984 9/23/13