DENTIFICATION

DESCRIPTION

SIGNIFICANCE

SOURCES

State of Connecticut CONNECTICUT HISTORICAL COMMISSION 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY: **Buildings & Structures**

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437 June-December 1981

FOR OFFICE USE ONLY Town No .: Site No. 249 UTM QUAD: IF NR SPECIES Actual Potential

1. ADDRESS

325 Long Hill Road (map 73, lot 10)

2. NAME

Chittenden

(historic) NAME

(present)

(common)

3. **USE** USE

(historic)

Private house

Private house, contracting

business (barns)

4. IF MOVED, WHEN AND FROM WHERE:



5. ARCHITECT

6. DATE

c1860

BUILDER STYLE

Greek Revival

7. ALTERATIONS

Screened wood shed attached to the rear; shingle siding; 6/6 window sash.

8. NOTABLE FEATURES Recessed entry; doorway with recessed panel pilasters, an entablature (with two rows of dentils) and sidelights; old paneled door.

9. ARCHITECTURAL-HISTORICAL

An elegant and well-detailed version of the Greek Revival style, this house has a full pedimented cornice with a decorative, rectangular gable window and a doorway with two rows of dentils in the wide entablature that spans not only pilasters but sidelights. A stone embankment and stone steps enhance the house.

According to a former owner, the house was built by Fred or Edward Chittenden about 1860.

10. SOURCES

Dorothy Whitfield Society; Jane P. Greene, interview with Harrison Landon, son of Howard Landon who bought the property in 1920.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source. 11. MATERIALS ☐ Clapboard ☐ Brick ☐ Stucco ☐ Asbestos Shingle ☐ Other: W Wood Shingle ☐ Fieldstone ☐ Asphalt Siding ☐ Concrete ☐ Board & Batten ☐ Cut Stone ☐ Cobblestone ☐ Aluminum/Vinyl 12. STRUCTURE ☐ Wood Frame: ☐ Masonry ☐ Iron or Steel □ Concrete Other: Post & Beam Balloon **13. ROOF** a. Ditched A Gable-front ☐ Hip ☐ Shed ☐ Other: ☐ Saltbox ☐ Cross-gable ☐ Flat Hip ☐ False Dormer ☐ Gambrel ☐ Mansard ☐ Flat ☐ Sawtooth b.

Tower(s) □ Monitor ☐ Dormered Gable □ Cupola □ Dome c. K Wood Shingle ☐ Asphalt Shingle ☐ Slate ☐ Metal ☐ Other: 21 14. NUMBER OF STORIES: **APPROXIMATE DIMENSIONS:** 17.5 ACRES LOT SIZE: 15. CONDITION: Exterior □ Excellent Good ☐ Fair ☐ Poor ☐ Bad 16. CONDITION: Structure ☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad 17. OUTBUILDINGS (visible from public road) ☐ Carriage House ☑ Garage ☐ Shed(s) ☐ Shop(s) Other (well, stand, greenhouse, gazebo, privy, etc.): 18. LANDSCAPING (visible from public road) Garden Planted Grounds □ Terracing ☐ Plaza ☐ Court Pickett Fence PEAR Stone Wall(s) ☐ Iron Fence ☐ Post & Rail ☐ Other: 19. SURROUNDING ENVIRONMENT a.

Town Street b.

Commercial c. Ø Open D Wooded ☐ Rural □ Industrial Agricultural DRCHARDS ⊠ Semi-rural ☐ Lakefront ☐ Clustered Growth Residential Coastal □ Development ☐ Vacation, now or originally ☐ Salt marsh d.

Of outstanding scenic/architectural value Of scenic/architectural value Of supportive value to contiguous scenic/architectural area Neutral ☐ Other: 20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT ☐ Vital ☐ Supportive □ Neutral ☐ Other: 21. OWNERSHIP ☐ Public Private □ Interior accessible 249 TUDEX NO. 22. Name D. PENAR Date 7/7/8/ Photographer D. PENAR Negative Organization: Guilford Preservation Alliance P.O. Box 199, Guilford, Conn. 06437 CIFD'S NEG 23. THREATS TO BUILDING ☐ None Known ☐ Highways □ Vandalism □ Developers □ Zoning ☐ Private Owner ☐ Renewal □ Deterioration ☐ Other: 24. SUBSEQUENT EVALUATIONS

In all categories below, check more than one box if applicable.

DESCRIPTION

COMPILED BY

R OFFICE USE ONLY