

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator,
State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza,
2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORM	MATION							
Building Name (Comme	on) 406 Long Hill Roa	ad						
Building Name (Histori	c) William F. Cordts H	House						
Street Address or Locat								
			County New Haven					
Owner(s) David Sumr	merlin			Public	▼ Private			
PROPERTY INFOR	RMATION							
Present Use: Residenti	ial: single dwelling							
Historic Use: Resident	tial: single dwelling							
Accessibility to public	e: Exterior visible from	n public road?⊠`	Yes No					
Interior accessible?	☐Yes 🗵 No If y	es, explain						
Style of building Greek Revival			Date of Construction 1905 (Helander)					
Material(s) (Indicate use								
▼ Clapboard	Asbestos Siding	☐ Brick	☐ Wood Shingle		Asphalt Siding			
Fieldstone	☐ Board & Batten	☐ Stucco	Cobblestone Aluminum Siding		n Siding			
☐ Concrete (Typ	e)	☐ Cut Stone	(Type)	Other			
Structural System								
☒ Wood Frame	Post & Beam	Balloon	☐ Load bearing	masonry	Structur	ral iron or steel		
Other								
Roof (Type)								
☒ Gable	☐ Flat ☐	Mansard	☐ Monitor	□ Sa	Sawtooth			
Gambrel	Shed	Hip	Round	Other				
(Material)								
☐ Wood Shingle	Roll Asphalt	Tin	☐ Slate	\mathbf{X}	Asphalt Shingle			
☐ Built up	☐ Tile							
Number of Stories: 2	2. 1/2	Approximate Dime	ensions <u>25' x 40'</u>					
Structural Condition:	☐ Excellent	⊠ Good	☐ Fair	De	eteriorated			
Exterior Condition:	☐ Excellent	⊠ Good	☐ Fair	De De	☐ Deteriorated			
Location Integrity:	On original site	Moved	When?					
Alterations? X Yes	□ No □ If yes, explain: Addition added to north and west elevations							
FOR OFFICE USE:	Town #	Site #	UTM					
District: S NR If NR, Specify: Actual Potential								

Related outbuilding	gs or landscape f				
Barn	X Shed	☐ Garage	☐ Carriage House	Shop	Garden
Other lands	cape features or b	uildings:			
Surrounding Enviro	onment:				
Open land	Woodland	▼ Residential	☐ Commercial	☐ Industrial	⊠ Rural
⊠ High buildir	ng density	Scattered buil	dings visible from site		
• Interrelationship of	building and surr	oundings:			
road and terminates the street and to the	at a parking area northeast is the	a to the north of the intersection of Long	de of Long Hill Road. A house. A shed is loca g Hill Road and Apple t Drive. (See continuat	ted to the northwe Tree Lane. Just to t	st of the house. Across
• Other notable featu	res of building or	site (Interior and/or	Exterior)		
Greek Revival in style	e and sheathed i	n wooden clapboard	ble roof. The roof is co d siding. The façade fa nent, but it is not acces	aces east. A doorwa	ay is located in the
Architect Unknown]	Builder Unknown		
• Historical or Archite	ectural importance	e:			
Many of the Germa German immigrant the Billie Chittende	n immigrants wh s in Guilford exce n House, burned	no settled in the wes eeded all other grou shortly after the Co	tern parts of Connecti ps except Italians (Bax	cut were farmers. I tter 1985, 75). An e William Cordts bui	ed Cordts as a farmer. By 1910 the number of arlier house on this site It this house to replace an.
towncode=060&ur Connecticut: Joel H	niqueid=7519 on Ielander, 2008. <i>A</i> "A Study of Immi	October 22, 2015. I Ancestry.com. 1920 I Igrants to Guilford, (o://www.propertyreco Helander, Joel Eliot. "A United States Federal Connecticut 1850-1830	Treasury of Guilfor Census of Guilford, D." Dexter, MI: Thon	rd Places." Guilford, Connecticut. Baxter, nson-Shore Inc., 1985.
View East view of t	he house, came	era facing west.	N	egative on File	
Name Kristen Niete	ring			Date 10/22/2	2015
Organization Guilfor	d Preservation	Alliance			
Address 199 PO Bo	x Guilford, CT (06437			
• Subsequent field eva					
Latitude & Longitud	e: 41.29913, -72.	69768			
Threats to the build	ling or site:				
	_	□x7 1.1°			
None known	Highways	☐ Vandalism	☐ Developers ☐	Renewal P	rivate



HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

406 Long Hill Rd

Interrelationship of buildings and surroundings

Surrounding the property are nineteenth and twentieth century single-family dwellings.

Other notable features of building or site

The main entry has been relocated to another front facing door in a small addition to the north elevation, accessed by a raised porch. A large 32-pane window is located on the first story façade to the north of the unused front door. Second story fenestration consists of three symmetrically-spaced double-hung windows, all two-over-two. A single two-over-two double-hung window is centered in the façade attic gable. A narrow brick chimney extends up from the roof ridgeline. A series of additions extend off the north and west elevations of the main structure.

