

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
 59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
 Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
 June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No. 264				
UTM									
QUAD:									
DISTRICT					IF NR SPECIFY				
<input type="checkbox"/> S <input type="checkbox"/> NR					<input type="checkbox"/> Actual <input type="checkbox"/> Potential				

IDENTIFICATION

1. ADDRESS 108 Lovers Lane  
 (map 41, lot 32)

2. NAME Joseph Weld  
 (historic)  
 NAME  
 (common)

3. USE  
 (historic)  
 USE  
 (present) Private house

4. IF MOVED, WHEN AND FROM WHERE: Moved from  
 south side of Green to make way for  
 the Guilford Trust Company parking lot  
 August 1960



5. ARCHITECT  
 6. DATE 1755

BUILDER  
 STYLE Colonial

7. ALTERATIONS  
 Rear lean-to addition; chimney; Greek Revival doorway with  
 pilasters and a large entablature; screen door.

8. NOTABLE FEATURES  
 Frieze; 8/12 sash; stone foundation.

9. ARCHITECTURAL-HISTORICAL

Moved here from Whitfield Street, on the south side of the Green,  
 this house now has a deep front yard that gives it a rural appearance.  
 Its regular facade with two rows of windows of the same size make it  
 a good example of the mid 18th-century houses of Guilford's center  
 district.

Joseph Weld, its original owner, opened a barber shop on the south  
 side of the Green with permission from its proprietors.

DESCRIPTION

SIGNIFICANCE

SOURCES

10. SOURCES

Dorothy Whitfield Society '76; Steiner' Dana 99-134; 1852 Irvine  
 Map.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |   |                                     |                                      |   |                                 |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle         | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten       | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |  |   |                                   |   |                                 |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched   | <input type="checkbox"/> Gable-front                | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Saltbox      | <input type="checkbox"/> Cross-gable                | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel                 | <input type="checkbox"/> Mansard                    | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| <i>appears as modern addition N side of rear</i> |   |                                   |   |                                 |
| b. <input type="checkbox"/> Tower(s)             | <input type="checkbox"/> Monitor                    | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input type="checkbox"/> Wood Shingle         | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:  $2\frac{1}{2}$

APPROXIMATE DIMENSIONS:

LOT SIZE: approx. 1.25 acre

15. CONDITION: Exterior

- |   |                               |                               |                               |                              |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |                                 |                                  |                                  |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s)                      | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   |                                 |                                  |                                  |

18. LANDSCAPING (visible from public road)

- |   |  |                                     |                                      |                                 |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden        | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)              | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street                                   | b. <input type="checkbox"/> Commercial               | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial                  | <input checked="" type="checkbox"/> Wooded  |
| <input checked="" type="checkbox"/> Semi-rural                                       | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth  | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value                |  |   |
| <input checked="" type="checkbox"/> Of scenic/architectural value                    |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |   |                                    |                                     |                                  |                                 |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 264

22. Name

P. Odiseas

Date

7/23/81

Photographer

P. Odiseas

Date

7/23/81

Negative Roll 17.3

Organization:

Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

Giffel's Neg. Roll 17: 34a

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS



Addenda 1983

108 Lovers Lane

Sources: Shore Line Times, 25th August, 1960.