

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORN					
Building Name (Commo	on) 154 North Fair	Street			
Building Name (Historie	c) Edwin Flook Ho	ouse			
Street Address or Locat	ion 154 North Fai	Street			
Town/City Guilford		_ Village	(County New Haven	
Owner(s) Robert D. K	ane Jr.			Public	X Private
PROPERTY INFOR	MATION				
Present Use: Residenc	e: Single Family I	Dwelling			
Historic Use: Residence	ce: Single Family	Dwelling			
Accessibility to public	: Exterior visible f	rom public road?	Yes 🗌 No		
Interior accessible?	Yes 🗙 No	If yes, explain			
Style of building Verna	cular		Date of	Construction 1862 (He	elander)
Material(s) (Indicate use					
🔀 Clapboard	Asbestos Siding	Brick	Wood Shing	gle 📃 Asphalt S	Siding
Fieldstone	□ Board & Batten □ Stucco □ Cobblestone □ Aluminum Sidi				m Siding
Concrete (Type	e	Cut Stone	е (Туре)	
Structural System					
🗙 Wood Frame	Post & Beam	Balloon	Load bearing	masonry Structu	ral iron or steel
Other					
Roof (<i>Type</i>)					
X Gable	🔲 Flat	☐ Mansard	Monitor	Sawtooth	
Gambrel	Shed	🗖 Hip	Round	Other	
(Material)					
Wood Shingle	🗌 Roll Aspha	lt 🗌 Tin	Slate	🗙 Asphalt Shingle	2
🗖 Built up	Tile	Other			
Number of Stories: 2		Approximate Dime	ensions <u>28' x 54'</u>		
Structural Condition:	Excel		🗌 Fair	Deteriorated	
Exterior Condition:	Excell	ent 🛛 Good	🗌 Fair	Deteriorated	
Location Integrity:	On original site	Moved	When?		
Alterations? X Yes	No If	ves, explain: Porch ex	ktended, north and	south additions, gara	ge added
FOR OFFICE USE:	Town #	Site #	UTM		
	District: S	□NR □If NR,	Specify: A	ctual	

PROPERTY INFORMATION (CONT'D)

Related outbuilding	gs or landscape fea	atures:			
Barn	🗙 Shed	🗙 Garage	Carriage House	Shop	Garden
Other lands	cape features or bu	ildings:			
Surrounding Enviro	onment:				
Open land	Woodland	Residential	X Commercial	Industrial	Rural
🗙 High buildir	ng density	Scattered build	dings visible from site		
• Interrelationship of	building and surro	undings:			
Located on a .25 acr	e parcel, this south	neast facing house	is on the west side of t	he northern part c	of North Fair Stre

Located on a .25 acre parcel, this southeast facing house is on the west side of the northern part of North Fair Street, where it becomes a one way after the intersection with Cherry Street. It is just south of the intersection with North Street in a residential neighborhood. There are many houses and is also located behind, or north of, a retail plaza that faces Boston Post Road. A small driveway is located on the south side of the house in front of a one car garage.

• Other notable features of building or site (Interior and/or Exterior)

Built in 1862, this two story Vernacular style house sits atop a stone brick foundation and is sheathed in light blue clapboards. The side gable roof is covered with asphalt shingles and has two chimneys. The oldest part of the house is the north section with four six over one hung sash windows across the second floor level. A full facade porch (north half is an addition) is held up by simple square columns. The northernmost bay's second story is also an addition. (See C.S.)

Architect _ Builder Unknown

• Historical or Architectural importance:

North Fair Street was laid out within a decade after the founding of Guilford as a thru way between Petticoat Lane and Crooked Lane. An earlier house stood on this property which was owned by Torrey Scranton, George Landon, Thaddeus W. Hanlon, Thomas Smith and then Elliott W. Gregory. English immigrant Edwin Flook then bought the property and was the first owner of this house in 1862. Widow Anna Tuttle (Mrs. Hezekiah Tuttle) owned it just a year later after her husband died in the Civil War. Her daughter, Elizabeth Tuttle, was the next owner followed by Julia B. Johnson, an African American wash woman. See House Dating Dossier for complete list of owners.

• Sources:

Helander, Joel Eliot, "A Treasury of Guilford Places," Guilford, CT: Joel Helander, 2008; Helander, Joel, "House Dating Dossier," 1985; Property card obtained at http://www.propertyrecordcards.com/PropertyResults.aspx? towncode=060&uniqueid=3270 on October 29, 2015.

Photographer				Date 01/31/2015		
View East, camera facing west				Negative on File		
Name Jordan Sorensen						
	ford Preservation A	lliance				
	199 Guilford, CT 06					
• Subsequent field	evaluations:					
Latitude: 41.2893 Longitude: -72.68						
Threats to the bu	ilding or site:					
None known	Highways	Vandalism	Developers	Renewal	Private	
Deterioration	Zoning	Other		Explanation		



State Historic Preservation Office

HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

154 North Fair Street

Notable Features Continued

A small one story addition is attached to the south side elevation and has a door entry and two six over six hung sash windows. The southernmost section (also an addition) has five six pane fixed windows on the second story level and three six over six hung sash windows on the first level next to a garage door.



