

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No. 286				
UTM									
QUAD:									
DISTRICT					IF NR. SPECIFY				
<input type="checkbox"/> S <input type="checkbox"/> NR					<input type="checkbox"/> Actual <input type="checkbox"/> Potential				

IDENTIFICATION

1. ADDRESS 323 North River Street
(map 46, lot 69)
2. NAME
(historic) Eleazer Woodruff
NAME
(common)
3. USE
(historic)
USE
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE c1846
- BUILDER
STYLE Greek Revival
7. ALTERATIONS
South side wing; some 2/2 sash.
8. NOTABLE FEATURES
Rectangular gable window (with decorative muntins).

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL
A fine example of a simple plan enlarged by a cross-gable wing, this house is an attractive expression of mid 19th century building in Guilford. A small barn with a ventilation cupola adds to the rural flavor of this house on a quiet street near the Town Millpond.

SOURCES

10. SOURCES
Dorothy Whitfield Society.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|-----------------------------------------------|-------------------------------------|--------------------------------------|-------------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|----------------------------------------|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|------------------------------------------|-----------------------------------------------------|-----------------------------------|-----------------------------------------|---------------------------------|
| a. <input type="checkbox"/> Pitched | <input checked="" type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input checked="" type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS:

LOT SIZE: 2 ACRES (APPROX)

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|------------------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|------------------------------------------|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|-------------------------------------------------------|-----------------------------------------|---------------------------------|----------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|-----------------------------------------------------|----------------------------------------|-------------------------------------|-------------------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input checked="" type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input checked="" type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--------------------------------------------------------------------------------------|------------------------------------------------------|---------------------------------------------|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input checked="" type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input checked="" type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|-----------------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|-----------------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---------------------------------------------|----------------------------------------------|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---------------------------------------------|----------------------------------------------|

INDEX NO. 286

22. Name D. PENAR

Date 7/15/81

Photographer D. PENAR

Date 7/15/81

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Outbdg 21:13
Negative 12:9

Outbdg 21:13
GLFD'S NEG 12:9

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|----------------------------------------|----------------------------------------|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY