

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
 59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
 Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
 June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No. 293				
UTM	:	:	:	:	:	:	:	:	:
QUAD:									
DISTRICT					IF NR SPECIFY				
<input type="checkbox"/> S <input type="checkbox"/> NR					<input type="checkbox"/> Actual <input type="checkbox"/> Potential				

IDENTIFICATION

1. ADDRESS 60 Nortontown Road
 (map 82, lot 6)
2. NAME
 (historic)
 NAME
 (common)
3. USE
 (historic)
 USE
 (present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE cl830
7. ALTERATIONS
 Side additions.

BUILDER
STYLE Vernacular

SIGNIFICANCE

8. NOTABLE FEATURES
 Overhanging eaves with a moulding below; central brick chimney; 6/6 sash; doorway with slender pilasters and a stylized entablature; front porch with square post (later addition?); stone foundation.
9. ARCHITECTURAL-HISTORICAL
 Practically devoid of ornament, the simplicity of this small house becomes its dominant feature. Later additions are set well back. The narrow three-bay width is most unusual for a two-story central chimney house. Set in remote marginal farm and woodland, it is a well-proportioned and interesting rural house.
 The name of Eber S. Hotchkiss is assigned to this property on the 1852 Map. Eber Hotchkiss, a shipwright, built his first vessel, a sloop, in the woods on his farm located "about three miles north of the East River Bridge" circa 1835. He then established a yard south of the Bridge where he built and launched a total of 32 vessels, according to his grandson, Charles O. Hotchkiss of Deep River.

SOURCES

10. SOURCES
 1852 Map; Shore Line Times, 4 December 1913; Steiner Scrapbook Vol 1, p.50

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 2 acres

15. CONDITION: Exterior

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|--|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input checked="" type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|--|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|---|---|--|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | <u>Corn crib (seen only)</u>
<u>barns</u> | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|--|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input checked="" type="checkbox"/> Picket Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--|--|---|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input checked="" type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input checked="" type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input checked="" type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input checked="" type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input type="checkbox"/> Important | <input checked="" type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 292

22. Name P. Odiseas

Date 7/15/81

Photographer P. Odiseas

Date 7/15/81 Negative R 9:29

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

At's Neg. R. 9: 29A

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS