

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORN					
Building Name (Commo	on) 279 Old Whitfie	eld Street			
Building Name (Historia	e) Peter M. O'Sulliv	/an House			
Street Address or Locati	on 279 Old Whitfie	eld Street			
Town/City Guilford		Village	Co	unty New Haven	
Owner(s) Nancy V. El	derbaum Family T	rust		Public	X Private
PROPERTY INFOR	MATION				
Present Use:	e: Single Family D	welling			
Historic Use: Residence					
Accessibility to public	: Exterior visible fr	om public road?	Yes 🗌 No		
Interior accessible?	Yes X No I	f yes, explain			
Style of building Greek	Revival		Date of 0	Construction 1875 (He	lander)
Material(s) (Indicate use					
X Clapboard	Asbestos Siding	Brick	Wood Shingle	Asphalt S	iding
Fieldstone	Board & Batten	Stucco	Cobblestone	Aluminur	n Siding
Concrete (Type	e)	Cut Stone	е (Туре)	
Structural System					
🗙 Wood Frame	🗌 Post & Beam	☐ Balloon	Load bearing ma	asonry Structur	ral iron or steel
Other		_			
Roof (<i>Type</i>)					
X Gable	Flat	Mansard	Monitor	Sawtooth	
Gambrel	Shed	🗌 Hip	Round	Other	
(Material)					
Wood Shingle	Roll Asphal		Slate	Asphalt Shingle	
🗖 Built up	Tile		chitectural Shingles		
Number of Stories: $\frac{2}{}$		Approximate Dime	ensions <u>40' x 37'</u>		
Structural Condition:	Excelle	ent 🛛 Good	🗌 Fair	Deteriorated	
Exterior Condition:	Excelle	nt 🛛 Good	🗌 Fair	Deteriorated	
Location Integrity:	On original site	Moved	When?		
Alterations? Yes	🗙 No 🛛 If ye	es, explain:			
FOR OFFICE USE:	Town #	Site #	UTM		
	District: S	\square NR \square If NR,	Specify: Actu	al Potential	

PROPERTY INFORMATION (CONT'D)

Related outbuildings or landscape features:							
Barn	Shed	Garage	Carriage House	Shop	Garden		
Other landsca	pe features or buil	dings:					
Surrounding Environ	ment:						
Open land	Woodland	Residential	Commercial	Industrial	Rural		
🗙 High building	density	Scattered build	lings visible from site				
• Interrelationship of b	wilding and surrou	indings:					
northwest half before a half mile southeast o	the railroad station of the Guilford Gro	on. It is located at t een and a half mile	s located on the south the corner of Old Whitfi northwest of the Guilf . (See Continuation She	ield and the end of ord Marina. The pro	Summer Street. It is		
• Other notable features of building or site (Interior and/or Exterior)							
Built in 1875, this two story Greek Revival style house sits atop a stone brick foundation and is sheathed in gray clapboard siding with white trim. The cross gable roof is covered in architectural shingles with a chimney on the southeast gable. On the front gable section of the building there is an elliptical fan light in the pediment. There are three six over six hung sash windows on the second floor. (See Continuation Sheet)							

Architect Unknown Builder _____ Alfred G. Hull (Helander)

• Historical or Architectural importance:

Peter M. and Mary O'Sullivan were the first owners of this house in 1875, under Mary's name. They were both born in Ireland and Peter worked as a foundry hand. He died in 1879 but left the house and property to Mary in his will. Alfred G. Hull, the builder, is also written into his will along with Mary, who was executrix. At that point, the house was sold to the next owner, Marshall Stevens (b. 1847) in 1879 with his wife Julia. Marshall worked as a house carpenter and they lived in this house until at least 1920. A later owner was Antonio Santa Maria.

• Sources:

Ancestry.com, U.S. Federal Census Records, 1870-1920; Ancestry.com, Connecticut Wills and Probate Records, 1874-1879; Helander, Joel Eliot, "A Treasury of Guilford Places," Guilford, CT: Joel Helander, 2008; Property card obtained at http://www.propertyrecordcards.com/PropertyResults.aspx?towncode=060&uniqueid=2097 on November 17, 2015.

Photographer				Date 11/07/2015		
$_{ m View}$ East, camera facing west				Negative on File		
Name Jordan Sorensen				Date 11/17/2015		
Organization Guil	ford Preservation A	lliance				
	199 Guilford, CT 0					
• Subsequent field	evaluations:					
Latitude: 41.2768 Longitude: -72.67						
Threats to the bu	ilding or site:					
None known	Highways	Vandalism	Developers	Renewal	Private	
Deterioration	Zoning	Other		Explanation		



State Historic Preservation Office

HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

279 Old Whitfield Street

Buildings and Surroundings Continued

A driveway and parking lot is located at the rear of the house, on the southwest side off of Summer Street.

Notable Features

Two more of the same windows are on the first floor with a door on the north end of the facade. All of the windows have a decorative lintel over the top and shutters with two panels on each. The door has a simple white surround with a small stoop and wood railings leading up to it. Two story pilasters are located on either corner of the front gable façade. On the cross gable are four more of the same windows and decorative features.

