

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No. 328
UTM	
QUAD:	
DISTRICT	IF NR. SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 44 Prospect Avenue
(map 2, lot 45)
2. NAME Frank E. Hayden
(historic)
NAME
(common)
3. USE
(historic)
USE Private house
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1909
7. ALTERATIONS
8. NOTABLE FEATURES
Alternating hip and gable roof dormers; decorative diamond pane window overhanging second story from the roof of the porch (supported by square posts).

BUILDER
STYLE Colonial Revival

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL
The overhanging gambrel-roofed second story makes a pleasant open porch for this seaside house as well as offering cool shade for the rooms behind it. Dormers with different roof styles add a playful note to the broad roof of this house. It is a good representative of the cottages built along the Sound in the early years of this century. Frank E. Hayden tore down two earlier cottages on this site and had this single large cottage built on the site.

SOURCES

10. SOURCES
Joel E. Helander, Oxpasture to Summer Colony.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- | | | | | |
|--|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl | |

12. STRUCTURE

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. ROOF

- | | | | | |
|---|--|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input checked="" type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: LOT SIZE: 135' X 110' (APPROX)

15. CONDITION: Exterior

- | | | | | |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- | | | | | |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. LANDSCAPING (visible from public road)

- | | | | | |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- | | | |
|--|---|---|
| a. <input type="checkbox"/> Town Street | b. <input type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input checked="" type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input checked="" type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input checked="" type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- | | | | | |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- | | | |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 328

22. Name P. Odiseas & D. Penar

Date 7/27/81

Photographer D. Penar

Date 7/27/81

Negative ROLL 19

Organization: Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 19

23. THREATS TO BUILDING

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. SUBSEQUENT EVALUATIONS

DESCRIPTION

COMPILED BY

FOR OFFICE USE ONLY