

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No. <b>337</b>
UTM	
QUAD:	
DISTRICT	IF NR. SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 22 South Fair Street  
(map 32, lot 52)
2. NAME George Bradley  
(historic)  
NAME  
(common)
3. USE  
(historic)  
USE  
(present) Private house
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1874
- BUILDER  
STYLE Greek Revival/Italianate
7. ALTERATIONS  
Window over the front door closed off; rear corner addition.

SIGNIFICANCE

8. NOTABLE FEATURES  
Segmental arched gable window; doorway with pilasters (leaf-like design in the capital area) and a stylized entablature with a leaf-like design in the frieze; stone foundation.
9. ARCHITECTURAL-HISTORICAL  
The Italianate taste of the 1870s imposed itself on Guilford with discretion. In the George Bradley house, the Greek Revival form is still evident, although details like the segmental arch of the gable window, the tall narrow windows, and the leafy decoration around the door point to newer trends. This house fits in well on a street of houses of similar scale.

SOURCES

10. SOURCES  
Dorothy Whitfield Society.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |   |                                     |                                      |   |                                 |
|---|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input checked="" type="checkbox"/> Clapboard | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle         | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten       | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |  |   |                                   |   |                                 |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input type="checkbox"/> Pitched      | <input checked="" type="checkbox"/> Gable-front     | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox         | <input type="checkbox"/> Cross-gable                | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel         | <input type="checkbox"/> Mansard                    | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)     | <input type="checkbox"/> Monitor                    | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES: 2 1/2 APPROXIMATE DIMENSIONS: LOT SIZE: 1/2 ACRE (APPROX)

15. CONDITION: Exterior

- |                                    |                               |  |                               |                              |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |  |   |                                  |
|---|---|--|---|----------------------------------|
| <input type="checkbox"/> Barn(s)                      | <input type="checkbox"/> Carriage House | <input checked="" type="checkbox"/> Garage | <input checked="" type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   |  |   |                                  |

18. LANDSCAPING (visible from public road)

- |  |   |                                     |                                      |                                 |
|--|---|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden                   | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)   | <input checked="" type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street                                   | b. <input type="checkbox"/> Commercial                                       | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial  | <input type="checkbox"/> Wooded             |
| <input type="checkbox"/> Semi-rural  | <input type="checkbox"/> Agricultural  | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth  | <input checked="" type="checkbox"/> Residential <u>POST OFFICE NEXT DOOR</u> | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally                         | <input type="checkbox"/> Salt marsh         |
| d. <input type="checkbox"/> Of outstanding scenic/architectural value                |  |   |
| <input checked="" type="checkbox"/> Of scenic/architectural value                    |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |                                |   |                                     |                                  |                                 |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input checked="" type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|---|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 337

22. Name D. PENAR

Date 7/28/81

Photographer D. PENAR

Date 7/28/81

Negative 21:8A

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD'S NEG. 21:10

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS