

State of Connecticut
CONNECTICUT HISTORICAL COMMISSION
59 South Prospect Street, Hartford 06106

HISTORIC RESOURCES INVENTORY:
Buildings & Structures

SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437
June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No. 351				
UTM									
QUAD:									
DISTRICT					IF NR SPECIFY				
<input type="checkbox"/> S <input type="checkbox"/> NR					<input type="checkbox"/> Actual <input type="checkbox"/> Potential				

IDENTIFICATION

1. ADDRESS 107 State Street
(map 47, lot 25)
2. NAME
(historic) Samuel Scranton, Jr.
NAME
(common)
3. USE
(historic) Private house
USE
(present) Offices and apartment
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1787
- BUILDER
STYLE Federal
7. ALTERATIONS
Aluminum/vinyl siding; external chimney and side additions; central chimney rebuilt; railing on front steps.

8. NOTABLE FEATURES
Triple window and a monumental door, enhanced by an unusually high and broad flight of front steps.

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL
The house of Samuel Scranton Jr. has a balanced facade with fine details; crown moldings making small entablatures for the windows-- a motif repeated in the broad Greek Revival entablature over the door. The width of the three-part window carries the strong center of symmetry up to the second floor. A handsome fence with squared posts, opening to broad front steps, demonstrates the importance of fencing in the overall appearance of a building in its setting. This is a good example of the town's Federal architecture, embellished, as was so often the case, by a later door.

SOURCES

10. SOURCES
Dorothy Whitfield Society '76; Tercentenary Committee; Dana Collection. Photograph: Guilford Library.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. **MATERIALS**

- | | | | | |
|---|-------------------------------------|--------------------------------------|--|---------------------------------|
| <input type="checkbox"/> Clapboard | <input type="checkbox"/> Brick | <input type="checkbox"/> Stucco | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete | <input type="checkbox"/> Asphalt Siding | |
| <input type="checkbox"/> Board & Batten | <input type="checkbox"/> Cut Stone | <input type="checkbox"/> Cobblestone | <input checked="" type="checkbox"/> Aluminum/Vinyl | |

12. **STRUCTURE**

- | | | | | |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam | | | | |
| <input type="checkbox"/> Balloon | | | | |

13. **ROOF**

- | | | | | |
|---|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front | <input type="checkbox"/> Hip | <input type="checkbox"/> Shed | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox | <input type="checkbox"/> Cross-gable | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer | |
| <input type="checkbox"/> Gambrel | <input type="checkbox"/> Mansard | <input type="checkbox"/> Flat | <input type="checkbox"/> Sawtooth | |
| b. <input type="checkbox"/> Tower(s) | <input type="checkbox"/> Monitor | <input type="checkbox"/> Cupola | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome |
| c. <input checked="" type="checkbox"/> Wood Shingle | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate | <input type="checkbox"/> Metal | <input type="checkbox"/> Other: |

14. **NUMBER OF STORIES:**

APPROXIMATE DIMENSIONS:

LOT SIZE: 1/2 ACRE
(APPROX)

15. **CONDITION: Exterior**

- | | | | | |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input checked="" type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|---|-------------------------------|-------------------------------|-------------------------------|------------------------------|

16. **CONDITION: Structure**

- | | | | | |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. **OUTBUILDINGS** (visible from public road)

- | | | | | |
|---|---|---------------------------------|----------------------------------|----------------------------------|
| <input type="checkbox"/> Barn(s) | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): | | | | |

18. **LANDSCAPING** (visible from public road)

- | | | | | |
|---|---|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden | <input type="checkbox"/> Terracing | <input type="checkbox"/> Plaza | <input type="checkbox"/> Court |
| <input type="checkbox"/> Stone Wall(s) | <input checked="" type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. **SURROUNDING ENVIRONMENT**

- | | | |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street | b. <input checked="" type="checkbox"/> Commercial | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural | <input type="checkbox"/> Industrial | <input type="checkbox"/> Wooded |
| <input type="checkbox"/> Semi-rural | <input type="checkbox"/> Agricultural | <input type="checkbox"/> Lakefront |
| <input type="checkbox"/> Clustered Growth | <input checked="" type="checkbox"/> Residential | <input type="checkbox"/> Coastal |
| <input type="checkbox"/> Development | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value | | |
| <input type="checkbox"/> Of scenic/architectural value | | |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area | | |
| <input type="checkbox"/> Neutral | | |
| <input type="checkbox"/> Other: | | |

20. **ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT**

- | | | | | |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. **OWNERSHIP**

- | | | |
|---------------------------------|----------------------------------|--|
| <input type="checkbox"/> Public | <input type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|----------------------------------|--|

22. **Name**

P. Odiseos

Photographer

P. Odiseos

Organization:

Guilford Preservation Alliance
P.O. Box 199, Guilford, Conn. 06437

Date 7/18/81

Date 7/18/81

Negative Roll 11:25

Glfd's Neg. Roll 11:25A

23. **THREATS TO BUILDING**

- | | | | | |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways | <input type="checkbox"/> Vandalism | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other: | |

24. **SUBSEQUENT EVALUATIONS**

Correct Historic Name: Samuel and Thomas Scranton.

This house was built by brothers, Thomas and Samuel Scranton, both farmers, on land purchased from their uncle who lived at 133 State Street. The brothers lived here until Samuel's death in 1806.

The property was deeded by Thomas Scranton, Jr., on 1st October, 1867 to his three children who sold it two years later to Joel Benton (see 110 State Street).

Sources: Shore Line Times, 4th July, 1957; Genealogy of the Descendants of John Scranton of Guilford, Connecticut.