

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
June-December 1981

FOR OFFICE USE ONLY									
Town No.:					Site No.: 346				
UTM									
QUAD:									
DISTRICT					IF NR SPECIFY				
<input type="checkbox"/> S <input type="checkbox"/> NR					<input type="checkbox"/> Actual <input type="checkbox"/> Potential				

IDENTIFICATION

1. **ADDRESS** 49 State St.  
(map 40, lot 100)
2. **NAME**  
(historic) Henry B. Beckwith  
**NAME**  
(common)
3. **USE**  
(historic)  
**USE**  
(present) Private house
4. **IF MOVED, WHEN AND FROM WHERE:**



DESCRIPTION

5. **ARCHITECT**
6. **DATE** c1927
7. **ALTERATIONS**

**BUILDER** Henry Beckwith and sons  
**STYLE** Irving and Walter  
Colonial Revival

SIGNIFICANCE

8. **NOTABLE FEATURES**  
Small boxed cornice with short returns; moulding along eaves and below; elliptical doorhood with brackets.
9. **ARCHITECTURAL-HISTORICAL**  
The doorway, with its elliptical door hood, is an attractive feature of this trim Colonial Revival house. Built in the early 20th century, the house relates well to its Colonial neighbors. This house was built by Henry Blatchley Beckwith and his sons, Walter and Irving.

SOURCES

10. **SOURCES**  
Interview George Beckwith, July 1982; Guilford Land Records; 1925 Sanborn Map.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |  |                                     |                                      |   |                                 |
|--|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input type="checkbox"/> Clapboard               | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten          | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |  |   |                                   |   |                                 |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input type="checkbox"/> Gable-front                | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox               | <input type="checkbox"/> Cross-gable                | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel               | <input type="checkbox"/> Mansard                    | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)           | <input type="checkbox"/> Monitor                    | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input type="checkbox"/> Wood Shingle       | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

1 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: 70' X 120'

15. CONDITION: Exterior

- |                                    |                               |  |                               |                              |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input checked="" type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|--|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |                                 |   |                                  |
|---|---|---------------------------------|---|----------------------------------|
| <input type="checkbox"/> Barn(s)                      | <input type="checkbox"/> Carriage House | <input type="checkbox"/> Garage | <input checked="" type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   |                                 |   |                                  |

18. LANDSCAPING (visible from public road)

- |  |  |                                     |                                      |                                 |
|--|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden        | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)   | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street                                   | b. <input type="checkbox"/> Commercial               | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial                  | <input type="checkbox"/> Wooded             |
| <input type="checkbox"/> Semi-rural  | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input type="checkbox"/> Clustered Growth  | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value     |  |   |
| <input type="checkbox"/> Of scenic/architectural value                               |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |                                |                                    |  |                                  |                                 |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|
| <input type="checkbox"/> Vital | <input type="checkbox"/> Important | <input checked="" type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|--------------------------------|------------------------------------|--|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 346

22. Name D. PENAR

Date FALL 1981

Photographer D. PENAR

Date FALL 1981

Negative 23:9A

Organization: Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

GLFD's NEG. 23:10

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS

Addenda 1983

49 State Street

Alterations: An addition to the dining-kitchen area was made in 1978.

Source: Mrs. Frances Canfield, owner, note dated 1983.