

HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORM	ATION					
Building Name (Commo	on) 78 State Street					
Building Name (Historic) Jason Evarts Hous	е				
Street Address or Locati	78 State Street					
Town/City Guilford	V	illage	C	ounty Nev	w Haven	
Owner(s) William Kne	erim and Danielle Sc	heltens			Public	X Private
PROPERTY INFOR						
Present Use:	e: Single Family Dwe	lling				
Historic Use: Residence	ce: Single Family Dwe	elling				
Accessibility to public	: Exterior visible from	public road?X	Yes 🗌 No			
Interior accessible?	Yes X No If ye					
Style of building Greek	Revival		Date of	Construc	tion 1850 (He	lander)
Material(s) (Indicate use						
Clapboard	Asbestos Siding	Brick	Wood Shing	le	Asphalt S	iding
Fieldstone	Board & Batten	Stucco	Cobblestone	9	X Aluminur	n Siding
Concrete (Type	e)	Cut Stone	е (Туре)	Other	
Structural System						
🗙 Wood Frame	Post & Beam	☐ Balloon	Load bearing i	masonry	Structur	ral iron or steel
Other						
Roof (<i>Type</i>)						
🗙 Gable	🗌 Flat 📃	Mansard	Monitor	🗌 Sa	wtooth	
Gambrel	Shed	Hip	Round	Other		
(Material)						
Wood Shingle	🗌 Roll Asphalt	Tin	Slate		Asphalt Shingle	
🗖 Built up	Tile					
Number of Stories: $\frac{2}{}$	A	pproximate Dime	ensions <u>24' x 68'</u>			
Structural Condition:	Excellent	🗙 Good	🗌 Fair	De De	eteriorated	
Exterior Condition:	Excellent	🗙 Good	🗌 Fair	De De	eteriorated	
Location Integrity:	On original site	Moved	When?			
Alterations? Yes	\square No \square If yes, e	explain:				
FOR OFFICE USE:	Town # 5	Site #	UTM			
	District: S	NR 🛛 If NR,	Specify: Ac	tual	Potential	

PROPERTY INFORMATION (CONT'D)

Related outbuildings	s or landscape fea	tures:			
🗌 Barn	Shed	🗙 Garage	Carriage House	Shop	Garden
Other landsc	ape features or bui	ldings:			
Surrounding Environ	nment:				
Open land	Woodland	Residential	Commercial	Industrial	Rural
🗙 High building	g density	Scattered build	dings visible from site		

• Interrelationship of building and surroundings:

Located on a .24 acre parcel, this east facing building is on the west side of State Street, to the north of the intersection with Market Street and south of the intersection with Boston Post Road. It's in a dense residential neighborhood about a quarter mile north east of the Guilford Green. A small driveway extends past the south side and ends at the middle of the house where there is a garage.

• Other notable features of building or site (Interior and/or Exterior)

Built in 1850, this two story Greek Revival house sits atop a concrete cinder block foundation and is sheathed in white aluminum siding. The front gable roof is covered in asphalt shingles and has one chimney on the ridgeline of the front section of the house. There is a small middle section where the roof line is slightly lower than the first and third section. A rectangular, recessed window with wide trim is located near the roof peak. (See Continuation Sheet)

Architect Unknown Builder Unknown

• Historical or Architectural importance:

The first owner of this house was Jason Evarts with his wife Rosette in 1850. Evarts worked as a peddler and butcher. As of 1858, the new owner was Edward E. Hall, a farmer, with his wife Elizabeth M. Hall, who owned it after her husband died, until around 1880. Adelaide and George Curtiss lived with the Halls (it is unclear if one of them was a child of Elizabeth and Edward) and then took over the house. Joseph Shepard lived in the house as of 1920 with his family and was a a wire chief for the telephone company.

• Sources:

Ancestry.com, United States Federal Census Records, 1860-1910; Helander, Joel Eliot, "A Treasury of Guilford Places," Guilford, CT: Joel Helander, 2008; Property card obtained at http://www.propertyrecordcards.com/PropertyResults. aspx?towncode=060&uniqueid=6619 on September 15, 2015.

Photographer				Date 1/31/2015			
$_{ m View}$ East, camera facing west				Negative on File			
Name Jordan Sorensen							
Organization Guilt	ford Preservation A	lliance					
	199 Guilford, CT 0						
• Subsequent field	evaluations:						
Latitude: 41.2867 Longitude: -72.68							
Threats to the bu	ilding or site:						
None known	Highways	Vandalism	Developers	Renewal	Private		
Deterioration	Zoning	Other		Explanation			



State Historic Preservation Office

HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

CONTINUATION SHEET

78 State Street

Notable Features

Three six over six hung sash windows are located on the second floor level while two are below it, with a large space in between. All the windows have black shutters. The front door entry is located on the south side elevation underneath a small porch. The porch has two columns for supports and a large entablature. A white wooden stoop leads up to the entry.

