

## **HISTORIC RESOURCES INVENTORY - BUILDING AND STRUCTURES**

Please send completed form to: Stacey Vairo, National Register and State Register Coordinator, State Historic Preservation Office, Department of Economic and Community Development, One Constitution Plaza, 2nd Floor, Hartford, CT 06103

\* Note: Please attach any additional or expanded information on a separate sheet.

GENERAL INFORM						
Building Name (Comme	on) 116 Whitfield	Street				
Building Name (Historie	<sub>c)</sub> Orlando Know	es House				
Street Address or Locat	ion 116 Whitfield	Street				
Town/City Guilford		Village		County New Have	en	
Owner(s) Arthur Carte	.r				ublic	X Private
PROPERTY INFOR	MATION					
Present Use: Retail						
Historic Use: Retail						
Accessibility to public	: Exterior visible	from public road?	Yes No			
Interior accessible?	XYes No		tail business open to			
Style of building Verna	icular		Date of	of Construction 18	57 (Hela	nder)
Material(s) (Indicate use	or location when appr					
Clapboard	Asbestos Sidin	g 🛛 Brick	Wood Shir	ngle 🗌 A	sphalt Sid	ing
Fieldstone	Board & Batte	n 🗌 Stucco	Cobblesto		luminum	0
Concrete (Type	e	_)	one ( Type		other Viny	I Siding
Structural System						
🗙 Wood Frame	🗌 Post & Beam	Balloon	Load bearing	g masonry	Structural	iron or steel
Other						
<b>Roof</b> ( <i>Type</i> )						
X Gable	🔲 Flat	☐ Mansard	Monitor	Sawtooth	1	
Gambrel	Shed	🗌 Hip	Round	Other_		
(Material)						
Wood Shingle	🗌 Roll Aspł	alt 🗌 Tin	Slate	🗙 Asphalt	Shingle	
🗖 Built up	Tile	Other				
Number of Stories: 2		Approximate D	imensions 47' x 19'			
Structural Condition:	Exce	llent 🛛 🗙 Goo	od 🗌 Fair	Deteriora	ted	
Exterior Condition:	Excel	lent 🛛 🖾 Goo	od 🗌 Fair	Deteriora	ted	
Location Integrity:	On original site	e Mov	wed When?_			
Alterations? Yes	X No If	yes, explain:				
FOR OFFICE USE:	Town #	Site #	UTM			
	District: S	□NR □If N	NR, Specify: $\Box A$	Actual P	otential	

### **PROPERTY INFORMATION (CONT'D)**

Related outbuildings	or landscape fea	tures:			
Barn	Shed	Garage	Carriage House	Shop	Garden
X Other landsca	pe features or buil	dings: <u>concrete pa</u>	atio on north side (19	50)	
Surrounding Environ	ment:				
Open land	Woodland	Residential	X Commercial	Industrial	Rural
🗙 High building	density	Scattered build	lings visible from site		
• Interrelationship of b	ouilding and surrou	indings:			
	ildings before Wh	itfield Street beco	de of Whitfield Street, j mes mainly residential t.		

• Other notable features of building or site (Interior and/or Exterior)

Although devoid of all ornamentation, this white, Vernacular style building has vinyl siding and a brick foundation measuring forty seven feet long and nineteen feet wide. The 1857 building faces southeast and has a front gable roof covered in asphalt shingles. On the front gable there are two bay windows on either side of the front entry door with 12 over 30, 16 over 40, and 4 over 10 fixed sash windows on each bay. (See Continuation Sheet)

, , , Unknown	Builder
Architect	Builder

• Historical or Architectural importance:

Built in 1857 as a meat market, Orlando L. Knowles was the first owner of this building. Based on census records, it can be determined that the Knowles family lived on the second floor, above the meat market. Frank Knowles, Orlando's son, grew up in the house and later became the founder of the Knowles-Lombard Company in the 1920s. The successful company primarily canned pumpkins and tomatoes and made "grit" for poultry farmers, along with selling its subdivided real estate on Tuttle's Point beginning in 1925. Later in the nineteenth century, Knowles lost the house due to indebtedness and the Roman Catholic church acquired the building, used as the first chapel before the building on the corner of High and Whitfield Streets was built (See 161 Whitfield St). (See Continuation Sheet)

#### • Sources:

Ancestry.com. 1870 United States Federal Census [database on-line]. Provo, UT, USA: Ancestry.com Operations, Inc., 2009. Helander, Joel, "Treasury of Guilford Places" Self Published:Guilford, CT, 2008; Images reproduced by FamilySearch; Guilford Preservation Alliance, "Significant Structures Fifty Years Old or More, Guilford, Connecticut" accessed at http://guilfordpreservation.org/WordPress/illustrated-survey on March 27, 2015 (See Continuation Sheet)

Photographer							
$_{ m View}$ Southeast v	view, camera facing	g northwest		Negative on Fil	e		
Name Jordan Sorensen				Date 3/29/2015			
Organization Guil	ford Preservation A	lliance					
	199 Guilford, CT 0						
• Subsequent field	evaluations:						
Latitude: 41.2806 Longitude: -72.68							
Threats to the bu	ilding or site:						
None known	Highways	Vandalism	Developers	Renewal	Private		
Deterioration	Zoning	Other		Explanation			



State Historic Preservation Office

# HISTORIC RESOURCE INVENTORY – BUILDINGS AND STRUCTURES

**CONTINUATION SHEET** 

**116 Whitfield Street** 

### **Notable Features Continued**

Directly above is a second story section extended past the main portion of the building with a paired double hung sash window on the front and one on both side elevations.

### **Historical/Architectural Significance**

This building was sold to its present owner, lawyer Arthur Carter, in 1979. Currently, the business Lis a lis salon is located on the first floor.

### **Sources Continued**

Property card found at

http://www.propertyrecordcards.com/PropertyResults.aspx?towncode=060&uniqueid=1056 on March 27, 2015





Guilford Keeping Society Archives, n.d.